

County Surveyor's Record, Douglas County, Oregon

16728

Remonumentation of Certain Original Corner Points,
T. 20 S., R 8 W., Willamette Meridian, Oregon

31

CHAINS

The 1/4 sec. cor. of secs. 14 and 23, monumented with an iron post, 1 in. diam., firmly set, projecting 10 ins. above ground, with brass cap mkd.

$$\frac{1}{4} \begin{array}{l} S 14 \\ S 23 \end{array}$$

1954

from which the remains of the bearing tree marked in 1954

A burned and sawed cedar stump, 45 ins. diam., bears N. 37° E., 97 lks. dist., no marks remaining on burned blaze. Rescribed 1/4 S14 BT on new blaze.

and a new bearing tree

A burned chinquapin, 9 ins. diam., bears S. 61 1/2° W., 13 lks. dist., mkd. 1/4 S23 BT.

Set a 6 ft. steel fence post alongside the iron post.

The 1/4 sec. cor. of secs. 14 and 15, monumented with an iron post, 1 in. diam., firmly set, projecting 5 ins. above ground, with brass cap mkd.

$$\frac{1}{4} \begin{array}{l} S 15 \\ S 14 \end{array}$$

1954

from which the remains of the bearing trees marked in 1954

A root hole, bears S. 41° E., 50 lks. dist., with a down maple alongside, 20 ins. diam., with healed blaze. (Record, 40 lks.)

An alder, 15 ins. diam., bears S. 56 1/2° W., 43 lks. dist., with scribe marks 1/4 S15 BT visible on bark.

and a new bearing tree

A maple, 20 ins. diam., bears S. 21° E., 59 lks. dist., mkd. 1/4 S14 BT.

Set a 6 ft. steel fence post alongside the iron post.

The cor. of secs. 10, 11, 14, and 15, monumented with an iron post, 2 ins. diam., firmly set, projecting 12 ins. above ground, with brass cap mkd.

$$\begin{array}{l} T 20 S R 8 W \\ S 10 | S 11 \\ S 15 | S 14 \end{array}$$

1954

from which the remains of the bearing trees marked in 1954

An alder, 9 ins. diam., bears North, 12 lks. dist., with scribe marks T20S R8W S11 BT visible on bark. (Record, N. 5 1/2° E.)