

# County Surveyor's Record, Douglas County, Oregon

16732

Remonumentation of Certain Original Corner Points,  
T. 20 S., R. 8 W., Willamette Meridian, Oregon

CHAINS

1/4  $\frac{S\ 27}{S\ 34}$   
1950

from which the remains of the bearing trees marked in 1950

A root hole, bears N. 71-1/2° W., 40 lks. dist., with the charred remains of a down hemlock alongside, no marks remaining.

A root hole, bears S. 30-1/4° E., 80 lks. dist., with down and burned fir stump alongside, 31 ins. diam., no marks remaining on burned blaze.

and new bearing trees

A burned cedar, 20 ins. diam., bears N. 25° E., 72 lks. dist., mkd. 1/4 S27 BT.

A burned sawed fir stump, 25 ins. diam., bears S. 10° E., 140 lks. dist., mkd. 1/4 S34 BT.

Set a 6 ft. steel fence post alongside the iron post.

(Rehabilitating corners established by William P. Wright, in 1884, and remonumented by Thomas A. Tillman, in 1950)

The 1/4 sec. cor. of secs. 27 and 28, monumented with an iron post, 1 in. diam., firmly set, projecting 12 ins. above ground, with brass cap mkd.

1/4  
S 28 | S 27  
1950

from which the remains of the original bearing tree

A burned and decayed hemlock stump, 16 ins. diam., bears S. 87° W., 19 lks. dist., no marks remaining.

and the remains of the bearing trees marked in 1950

A sawed and burned fir stump, 38 ins. diam., bears S. 31° E., 43 lks. dist., no marks remaining on burned blaze. Rescribed 1/4 S27 BT on new blaze.

A root hole, bears N. 37° W., 59 lks. dist., with a down and sawed fir stump alongside, 24 ins. diam., no marks remaining.

and a new bearing tree

A sawed and burned fir stump, 25 ins. diam., bears N. 73° W., 82-1/2 lks. dist., mkd. 1/4 S28 BT.

Set a 6 ft. steel fence post alongside the iron post.

The cor. of secs. 21, 22, 27, and 28, monumented with