

# County Surveyor's Record, Douglas County, Oregon

16733

Remonumentation of Certain Original Corner Points,  
T. 20 S., R. 8 W., Willamette Meridian, Oregon

CHAINS

an iron post, 2 ins. diam., firmly set, projecting 8 ins. above ground, with brass cap mkd.

T 20 S R 8 W  
S 21 | S 22  
S 28 | S 27  
1950

from which the remains of the bearing trees marked in 1950

An alder snag, 15 ins. diam., bears N. 45° E., 123 lks. dist., no marks remaining on burned blaze.

A burned alder snag, 14 ins. diam., bears S. 46° E., 82 lks. dist., no marks remaining on burned blaze.

A burned hemlock snag, 12 ins. diam., bears S. 31 W., 81 lks. dist., no marks visible on open and burned blaze. Rescribed T20S R8W S28 BT on new blaze.

A burned cedar snag, 42 ins. diam., bears N. 83-1/2° W., 70 lks. dist., with fragmentary scribe marks visible on burned blaze. Rescribed T20S R8W S21 BT on new blaze.

and an unrecorded bearing tree

A burned hemlock, 11 ins. diam., bears S. 66° W., 63-1/2 lks. dist., no marks remaining on burned blaze.

and new bearing trees

A burned cedar snag, 45 ins. diam., bears N. 13° E., 175 lks. dist., mkd. T20S R8W S22 BT.

A burned fir, 45 ins. diam., bears S. 52° E., 251 lks. dist., mkd. T20S R8W S27 BT.

Set a 5 ft. steel fence post alongside the iron post.

(Rehabilitating corners reestablished  
by Thomas A. Tillman, in 1950)

The 1/4 sec. cor. of secs. 22 and 27, monumented with an iron post, 1 in. diam., firmly set, projecting 12 ins. above ground, with brass cap mkd.

1/4  $\frac{S\ 22}{S\ 27}$   
1950

from which the remains of the bearing trees marked in 1950

A root hole, bears N. 10° E., 39 lks. dist., with a down and burned fir alongside, 17 ins. diam., no marks remaining on burned blaze.

A burned root crown, 26 ins. diam., bears