

# County Surveyor's Record, Douglas County, Oregon

16734

Remonumentation of Certain Original Corner Points,  
T. 20 S., R. 8 W., Willamette Meridian, Oregon

CHAINS

S. 89° E., 13 lks. dist., no marks  
remaining on burned blaze.

and new bearing trees

A burned fir, 20 ins. diam., bears  
N. 78° W., 84 lks. dist., mkd. 1/4 S22 BT.

A burned cedar, 15 ins. diam., bears  
S. 15-1/2° W., 42-1/2 lks. dist., mkd. 1/4 S27 BT.

Set a 5 ft. steel fence post alongside the  
iron post.

The 1/4 sec. cor. of secs. 21 and 22, monumented with an  
iron post, 1 in. diam., firmly set, projecting 10 ins.  
above ground, with brass cap mkd.

1/4  
S 21 | S 22  
1950

from which the remains of the bearing trees marked in  
1950

A cedar, 26 ins. diam., bears S. 29-3/4° E.,  
17 lks. dist., with scribe marks 1/4 S  
visible on partially healed blaze.

A root hole, bears S. 61-1/2° W., 107 lks.  
dist., with a down fir alongside, 40 ins.  
diam., no marks remaining on burned blaze.

and a new bearing tree

A fir stump, 48 ins. diam., bears S. 62° W.,  
132 lks. dist., mkd. 1/4 S21 BT.

Set a 6 ft. steel fence post alongside the  
iron post.

(Rehabilitating a corner established by  
William P. Wright, in 1884, and remonumented  
by Thomas A. Tillman, in 1950)

The cor. of secs. 15, 16, 21, and 22, monumented with  
an iron post, 2 ins. diam., firmly set, projecting 10  
ins. above ground, with brass cap mkd.

T 20 S R 8 W  
S 16 | S 15  
S 21 | S 22  
1950

from which the remains of the original bearing trees

A burned fir stump, 20 ins. diam., bears  
N. 44-1/2° E., 33 lks. dist., no marks  
remaining.

A burned cedar, 46 ins. diam., bears  
S 33-3/4° E., 26 lks. dist., no marks  
remaining. Rescribed T20S R8W S22 BT  
on new blaze.

A burned fir snag, 76 ins. diam., bears