

County Surveyor's Record, Douglas County, Oregon

16737

Remonumentation of Certain Original Corner Points,
T. 20 S., R. 8 W., Willamette Meridian, Oregon

CHAINS

$$\begin{array}{r} \text{S } 10 \\ \text{S } 15 \end{array} \frac{1}{4} \\ 1954$$

from which bearing trees marked in 1954

A cedar, 60 ins. diam., bears N. 57° E.,
36 lks. dist., with scribe marks 1/4 S10 B
visible on open blaze. Rescribed BT on
new blaze.

A cedar, 57 ins. diam., bears S. 22° W.,
71 lks. dist., with scribe marks 1/4 S T
visible on open and burned blaze. Rescribed
1/4 S15 BT on new blaze.

Set a 6 ft. steel fence post alongside the iron
post.

The 1/4 sec. cor. of secs. 9 and 10, monumented with an
iron post, 1 in. diam., firmly set, projecting 8 ins.
above ground, with brass cap mkd.

$$\begin{array}{r} 1/4 \\ \text{S } 9 \mid \text{S } 10 \\ 1954 \end{array}$$

from which new bearing trees

A burned fir snag, 53 ins. diam, bears
S. 36° E., 71 lks. dist., mkd. 1/4 S10 BT.

A burned fir snag, 38 ins. diam, bears
N. 11° W., 50 lks. dist., mkd. 1/4 S9 BT.

Set a 6 ft. steel fence post alongside the
iron post.

The cor. of secs. 3, 4, 9, and 10, monumented with an
iron post, 1 ins. diam., firmly set, projecting 18 ins.
above ground, with brass cap mkd.

$$\begin{array}{r} \text{T } 20 \text{ S } \text{R } 8 \text{ W} \\ \text{S } 4 \mid \text{S } 3 \\ \text{S } 9 \mid \text{S } 10 \\ 1954 \end{array}$$

from which bearing trees marked in 1954

A fir, 50 ins. diam., bears N. 47-1/2° E.,
51 lks. dist., no marks remaining on burned
blaze. Rescribed T20S R8W S3 BT on new blaze.

A fir, 34 ins. diam., bears S. 78 1/2° E.,
51 lks. dist., with healed blaze.

A fir, 60 ins. diam., bears S. 33° W.,
111 lks. dist., with burned blaze. Rescribed
T20S R8W S9 BT on new blaze.

A fir, 52 ins. diam., bears N. 77° W.,
60 lks. dist., with burned blaze. Rescribed
T20S R8W S4 BT on new blaze.

The 1/4 sec. cor. of secs. 3 and 10, monumented with an
iron post, 1 in. diam., firmly set, projecting 3 ins.