

# County Surveyor's Record, Douglas County, Oregon

16738

Remonumentation of Certain Original Corner Points,  
T. 20 S., R. 8 W., Willamette Meridian, Oregon

CHAINS

above ground, with brass cap mkd.

$$\frac{1}{4} \begin{array}{l} S 3 \\ S 10 \end{array}$$

1954

from which the remains of the bearing trees marked in 1954

A burned maple, 17 ins. diam., bears  
N. 79° E., 37 lks. dist., with scribe  
marks 1/4 S visible on burned blaze.

A maple snag, 15 ins. diam., bears S. 73° W.,  
48 lks. dist., with healed blaze.

and a new bearing tree

A cedar, 30 ins. diam., bears S. 15° E.,  
87 lks. dist., mkd. 1/4 S10 BT.

---

The 1/4 sec. cor. of secs. 3 and 4, monumented with an  
iron post, 1 in. diam., firmly set, projecting 6 ins.  
above ground, with brass cap mkd.

$$\frac{1}{4}$$

$$S 4 \begin{array}{l} S 3 \end{array}$$

1954

from which the remaining bearing tree marked in 1954

A fir, 37 ins. diam., bears S. 66 1/4° E.,  
22 lks. dist., no marks remaining on burned  
blaze. Rescribed 1/4 S3 BT on new blaze.

and a new bearing tree

A sawed fir stump, 60 ins. diam., bears  
N. 56° W., 16 lks. dist., mkd. 1/4 S4 BT.

---

(Rehabilitating corners established by  
William P. Wright, in 1884, and remonumented  
by Thomas A. Tillman, in 1950)

---

The 1/4 sec. cor. of secs. 32 and 33, monumented with an  
iron post, 1 in. diam., firmly set, projecting 10 ins.  
above ground, with brass cap mkd.

$$\frac{1}{4}$$

$$S 32 \begin{array}{l} S 33 \end{array}$$

1950

from which the remains of the original bearing trees

A cedar snag, 53 ins. diam., bears S. 30° W.,  
10 lks. dist., with healed blaze.

and the remains of the bearing tree marked in 1950

A burned fir, 33 ins. diam., bears N. 25° E.,  
61 lks. dist., with healed blaze.

and new bearing trees

A hemlock, 20 ins. diam., bears S. 52° E.,  
65 lks. dist., mkd. 1/4 S33 BT.