

County Surveyor's Record, Douglas County, Oregon

16741

Remonumentation of Certain Original Corner Points,
T. 20 S., R. 8 W., Willamette Meridian, Oregon

CHAINS

drill hole, in solid rock, with brass cap mkd.

1/4 $\frac{S\ 21}{S\ 28}$
T 20 S R 8 W
1967

from which a new bearing tree

A sawed cedar stump, 33 ins. diam., bears
S. 29 1/2° W., 151 lks. dist., mkd. 1/4 S28 BT.

Set a 5 ft. steel fence post alongside the iron
post.

(Rehabilitating corners established by
William P. Wright, in 1884 and remonumented by
Thomas A. Tillman, Joseph S. Gawron, Hans W. Thielsen,
and Raymond M. Bicknell, in 1953-54)

The 1/4 sec. cor. of secs. 20 and 21, monumented with an
iron post, 1 in. diam., firmly set, projecting 10 ins.
above ground, with brass cap mkd.

1/4
S 20 | S 21
1954

from which the remains of the original bearing trees

A fir snag, 62 ins. diam., bears N. 60° E.,
9 lks. dist., with healed blaze.

A fir snag, 21 ins. diam., bears S. 51° W.,
30 lks. dist., with healed blaze.

and the remains of the bearing tree marked in 1954

A fir snag, 21 ins. diam., bears S. 61 1/2° E.,
51 lks. dist., with healed blaze.

Set a 5 ft. steel fence post alongside the
iron post.

The cor. of secs. 16, 17, 20, and 21, monumented with an
iron post, 2 ins. diam., firmly set, projecting 6 ins.
above ground, with brass cap mkd.

T 20 S R 8 W
 $\frac{S\ 17 | S\ 16}{S\ 20 | S\ 21}$
1954

from which the remains of the original bearing trees

A sawed fir stump, 40 ins. diam., bears
S. 48° W., 72 lks. dist., no marks remaining
on burned blaze. (Record, 69 lks.)

A root hole, bears N. 61° W., 36 lks. dist.,
with a down maple, alongside, 30 ins. diam.,
with healed blaze.

and the remains of the bearing trees marked in 1954

A root hole, bears S. 28 3/4° E., 64 lks. dist.,