

# County Surveyor's Record, Douglas County, Oregon

16744

Remonumentation of Certain Original Corner Points,  
T. 20 S., R. 8 W., Willamette Meridian, Oregon

CHAINS

above ground, with brass cap mkd.

1/4  $\frac{S\ 9}{S\ 16}$   
1954

from which the remaining original bearing tree

A cedar, 34 ins. diam., bears S. 10° W.,  
30 lks. dist., with healed blaze.

and the bearing tree marked in 1954

A cedar, 33 ins. diam., bears N. 67 1/2° W.,  
36 lks. dist., with healed blaze.

Set a 5 ft. steel fence post alongside the  
iron post.

---

The 1/4 sec. cor. of secs. 8 and 9, monumented with an  
iron post, 1 in. diam., firmly set, projecting 4 ins.  
above ground, with brass cap mkd.

1/4  
S 8 | S 9  
1954

from which the remaining original bearing tree

An alder, 24 ins. diam., bears N. 27° W.,  
29 lks. dist., no marks visible on partially  
healed blaze.

and the remains of the bearing trees marked in 1954

A sawed hemlock stump, 35 ins. diam., bears  
S. 22 1/4° E., 79 lks. dist., with scribe marks  
1/4 S9 BT visible on open blaze.

A fir, 45 ins. diam., bears N. 11° W., 76 lks.  
dist., with healed blaze.

and a new bearing tree

A cedar, 12 ins. diam., bears N. 8 3/4° E.,  
70 lks. dist., mkd. 1/4 S9 BT.

Set a 5 ft. steel fence post alongside the  
iron post.

---

(Rehabilitating corners reestablished by  
Thomas A. Tillman, in 1950)

---

The 1/4 sec. cor. of secs. 31 and 32, monumented with an  
iron post, 1 in. diam., firmly set, projecting 3 ins.  
above ground, with brass cap mkd.

1/4  
S 31 | S 32  
1950

from which the remains of the bearing trees marked in  
1950

A burned fir snag, 32 ins. diam., bears  
S. 2 3/4° E., 83 lks. dist., with scribe marks