

# County Surveyor's Record, Douglas County, Oregon

16745

Remonumentation of Certain Original Corner Points,  
T. 20 S., R. 8 W., Willamette Meridian, Oregon

CHAINS

S32 visible on burned blaze.

and a new bearing tree

A burned and sawed hemlock stump, 18 ins.  
diam., bears S. 77° W., 79 lks. dist.,  
mkd. 1/4 S31 BT.

Set a 6 ft. steel fence post alongside the  
iron post.

(Rehabilitating corners established by  
William P. Wright, in 1884, and  
remonumented by Thomas A. Tillman, in 1950)

The cor. of secs. 29, 30, 31, and 32, monumented with an  
iron post, 2 ins. diam., firmly set, projecting 8 ins.  
above ground, with brass cap mkd.

T 20 S R 8 W
S 30   S 29
S 31   S 32
1950

from which the remains of the bearing trees marked in  
1950

A burned fir, 43 ins. diam., bears N. 47° E.,  
38 lks. dist., with healed blaze.

A burned cedar, 25 ins. diam., bears S. 74° E.,  
28 1/2 lks. dist., no marks visible on burned  
blaze. (Record, 30 lks.) Rescribed T20S  
R8W S32 BT on new blaze.

A burned fir, 60 ins. diam., bears S. 71° W.,  
33 lks. dist., with healed blaze.

A burned fir, 40 ins. diam., bears N. 38 3/4° W.,  
67 lks. dist., with healed blaze.

Set a 5 ft. steel fence post alongside the  
iron post.

The 1/4 sec. cor. of secs. 29 and 32, monumented with an  
iron post, 1 in. diam., firmly set, projecting 6 ins.  
above ground, with brass cap mkd.

1/4 S 29
S 32
1950

from which the remains of the original bearing trees

A root hole, bears N. 54° W., 15 lks. dist.,  
with a down fir alongside, 8 ins. diam.,  
no marks remaining.

A burned cedar stump, 55 ins. diam., bears  
S. 30° W., 11 lks. dist., no marks remaining  
on burned blaze. Rescribed 1/4 S32 BT on new  
blaze.

and the remains of the bearing tree marked in 1950

A burned fir stump, 27 ins. diam., bears