

County Surveyor's Record, Douglas County, Oregon

16747

Remonumentation of Certain Original Corner Points,
T. 20 S., R. 8 W., Willamette Meridian, Oregon.

CHAINS

from which the remains of the original bearing trees

A sawed fir stump, 10 ins. diam., bears
S. 55° E., 25 lks. dist., no marks remaining
on burned blaze.

and the remains of the bearing trees marked in 1950

A sawed fir stump, 10 ins. diam., bears
N. 10° E., 24 lks. dist., no marks remaining
on burned blaze. Rescribed T20S R8W S20
BT on new blaze.

A sawed fir stump, 30 ins. diam., bears
S. 71 1/2° W., 49 lks. dist., with healed
blaze.

A sawed fir stump, 10 ins. diam., bears
N. 36 1/2° W., 35 lks. dist., with healed blaze.

Set a 5 ft. steel fence post alongside the iron
post.

(Rehabilitating corners reestablished by
Thomas A. Tillman, in 1950)

The 1/4 sec. cor. of secs. 20 and 29, monumented with an
iron post, 1 in. diam., firmly set, projecting 10 ins.
above ground, with brass cap mkd.

$$\frac{1}{4} \frac{S \ 20}{S \ 29}$$

1950

from which the remains of the bearing trees marked in
1950

A fir snag, 62 ins. diam., bears N. 20° E.,
5 lks. dist., with healed blaze.

A hemlock snag, 27 ins. diam., bears
S. 31 3/4° W., 58 lks. dist., with scribe
marks 1/4 S29 visible on open and burned
blaze. Rescribed 1/4 S29 BT on new blaze.

The 1/4 sec. cor. of secs. 19 and 30, monumented with an
iron post, 1 in. diam., firmly set, projecting 4 ins.
above ground, with brass cap mkd.

$$\frac{1}{4} \frac{S \ 19}{S \ 30}$$

1950

from which the remains of the bearing trees marked in
1950

A fir, 28 ins. diam., bears N. 68 3/4° W.,
24 lks. dist., with healed blaze.

A root hole, bears S. 57 1/2° E., 37 lks. dist.,
with a down fir alongside, 24 ins. diam.,
with scribe marks 1/4 S30 BT visible on open
blaze.

and a new bearing tree