

# County Surveyor's Record, Douglas County, Oregon

16748

Remonumentation of Certain Original Corner Points,  
T. 20 S., R 8 W., Willamette Meridian, Oregon

CHAINS

A fir, 33 ins. diam., bears S. 19 3/4° W.,  
73 1/2 lks. dist., mkd. 1/4 S30 BT.

Set a 5 ft. steel fence post alongside the  
iron post.

(Rehabilitating corners established by  
William P. Wright, in 1884, and remonumented  
by Thomas A. Tillman, Joseph S. Gawron,  
Hans W. Thielsen, and Raymond M. Bicknell, in 1954)

The 1/4 sec. cor. of secs. 19 and 20, monumented with an  
iron post, 1 in. diam., firmly set, projecting 4 ins.  
above the ground, with brass cap mkd.

1/4  
S 19 | S 20  
1954

from which the remains of the original bearing trees

A cedar snag, 64 ins. diam., bears  
S. 53° E., 42 lks. dist., no marks  
remaining on burned blaze.

A fir snag, 85 ins. diam., bears  
N. 60° W., 47 lks. dist., no marks  
remaining on burned blaze.

and the remains of the bearing trees marked in 1954

A hemlock snag, 32 ins. diam., bears  
N. 82-3/4° E., 83 lks. dist., no marks  
remaining on burned blaze. Rescribed 1/4  
S20 BT on new blaze.

A fir snag, 28 ins. diam., bears N. 81-1/2° W.,  
51 lks. dist., with healed blaze.

Set a 5 ft. steel fence post alongside the iron post.

The cor. of secs. 17, 18, 19, and 20, monumented with an  
iron post, 2 ins. diam., firmly set, projecting 4 ins.  
above ground, with brass cap mkd.

T 20 S R 8 W  
S 18 | S 17  
S 19 | S 20  
1954

from which the remains of the original bearing trees

A burned fir snag, 20 ins. diam., bears  
N. 63° E., 70 lks. dist., with healed  
blaze.

A burned fir snag, 47 ins. diam., bears  
S. 77-1/2° E., 19 lks. dist., with healed  
blaze.

A burned fir snag, 57 ins. diam., bears  
S. 70° W., 54 lks. dist., no marks visible  
on decayed blaze. Rescribed T20S R8W S19 BT  
on new blaze.