

County Surveyor's Record, Douglas County, Oregon

16749

Remonumentation of Certain Original Corner Points,
T. 20 S., R. 8 W., Willamette Meridian, Oregon

CHAINS

A root hole, bears N. 76° W., 43 lks. dist.,
with a down fir alongside, 62 ins. diam.,
no marks visible.

and the remains of the bearing trees marked in 1954

A root hole, bears N. 79 1/2° E., 115 lks.
dist., with a down fir alongside, 45 ins.
diam., no marks visible.

A hemlock snag, 18 ins. diam., bears
S. 12 1/4° E., 34 lks. dist., no marks
remaining on burned blaze. Rescribed
T20S R8W S20 BT on new blaze.

A root hole, bears S. 49 1/2° W., 80 lks. dist.,
with a down fir alongside 52 ins. diam.,
no marks remaining on burned blaze.

and new bearing trees

A cedar snag, 50 ins. diam., bears N. 56° E.,
127 lks. dist., mkd. T20S R8W S17 BT.

A hemlock snag, 10 ins. diam., bears N. 16 1/2° W.,
35 1/2 lks. dist., mkd. T20S R8W S18 BT.

Set a 5 ft. steel fence post alongside the
iron post.

(Rehabilitating corners reestablished by
Thomas A. Tillman, Joseph S. Gawron,
Hans W. Thielsen, and Raymond M. Bicknell, in 1954)

The 1/4 sec. cor. of secs. 17 and 20, monumented with an
iron post, 1 in. diam., firmly set, projecting 6 ins.
above ground, with brass cap mkd.

$$1/4 \frac{S \ 17}{S \ 20}$$

1954

from which bearing trees marked in 1954

A fir, 48 ins. diam., bears N. 30° W.,
45 lks. dist., with healed blaze.

A fir, 43 ins. diam., bears S. 28° W.,
27 lks. dist., no marks remaining on
burned blaze. Rescribed 1/4 S20 BT on
new blaze.

Set a 5 ft. steel fence post alongside the
iron post.

(Rehabilitating a corner established by
William P. Wright, in 1884, and remonumented by
Thomas A. Tillman, Joseph S. Gawron, Hans W. Thielsen,
and Raymond M. Bicknell, in 1954)

The 1/4 sec. cor. of secs. 18 and 19, monumented with an
iron post, 1 in. diam., lying on the top of the ground,
with brass cap mkd.

$$1/4 \frac{S \ 18}{S \ 19}$$

1954