

# County Surveyor's Record, Douglas County, Oregon

Corrective Dependent Resurvey,  
 Portion of Subdivisional Lines,  
 T. 26 S., R. 8 W., Willamette Meridian, Oregon

16758

**CHAINS**

A fir snag, 52 ins. diam., bears S. 85° W., 28 lks. dist., no marks visible.

and remains of bearing trees mkd. by Tracy

A hemlock, 14 ins. diam., bears N. 57° E., 38 lks. dist., with fragmentary scribe marks visible on partially healed blaze.

A root hole, bears N. 43° W., 38 lks. dist., with down hemlock alongside, 12 ins. diam., with healed blaze.

and a new bearing tree

A hemlock, 4 ins. diam., bears N. 87° W., 41 lks. dist., mkd. X BT.

Land, mountainous.

Soil, rocky clay.

Timber, fir, cedar, hemlock, yew, alder, maple, madrone, chinquapin, and oak; undergrowth, arrowwood, fern, Oregon grape, vine maple, poison oak, hazel, blackberry, huckleberry, and rhododendron.

From the cor. of secs. 1, 6, 7, and 12, on the E. bdy. of the Tp., monumented with an iron post, 2 1/2 ins. diam., firmly set, projecting 6 ins. above ground, with brass cap mkd.

T 26 S	
T 8 W	R 7 W
S 1	S 6
S 12	S 7

1971

from which bearing trees mkd. by Peterson and Berry

A madrone, 7 ins. diam., bears S. 81 1/2° E., 27 lks. dist., with fragmentary scribe marks visible on bark blaze. (Record, S. 83° E.)

A fir, 18 ins. diam., bears S. 7 1/2° E., 39 lks. dist., with healed blaze. (Record, S. 5° E., 29 lks.)

A fir, 24 ins. diam., bears S. 37 1/2° W., 73 lks. dist., with healed blaze. (Record, S. 39° W., 41 lks.)

and new bearing trees

A fir, 7 ins. diam., bears N. 9° E., 36 1/2 lks. dist., mkd. T26S R7W S6 BT.

A fir, 5 ins. diam., bears N. 37 3/4° W., 53 lks. dist., mkd. X BT.

N. 89° 27' W., bet. secs. 1 and 12.

Descend 355 ft. over NW. slope, through heavy timber and dense undergrowth.

19.355

Point for the E 1/16 sec. cor. of secs. 1 and 12.