

County Surveyor's Record, Douglas County, Oregon

16757

Corrective Dependent Resurvey,
Portion of Subdivisional Lines,
T. 26 S., R. 8 W., Willamette Meridian, Oregon

CHAINS

From this point, the E 1/16 sec. cor. of secs. 1 and 12, erroneously established by Peterson and Berry in 1971, bears West, 0.09 chs. dist., monumented with an iron post, 2 1/2 ins. diam., firmly set, protruding 4 ins. above ground, with brass cap mkd. as described in the field notes of the resurvey.

Move the iron post to the corner point and

Reset the iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with brass cap mkd.

E 1/16 $\frac{S 1}{S 12}$
1983
1971

from which a bearing tree mkd. by Peterson and Berry

A grand fir, 12 ins. diam., bears S. 84 1/2° W.,
49 1/2 lks. dist., with healed blaze.

and a new bearing tree

A fir, 14 ins. diam., bears N. 53 1/2° E.,
37 1/2 lks. dist., mkd. E 1/16 S1 BT.

Destroy the marks on the NE. bearing tree mkd. in 1971.

Descend 110 ft. over NW. slope.

21.10 Hubbard Creek Road, paved, 40 lks. wide, bears N. 20° E. and S. 20° W.

25.50 Hubbard Creek, 60 lks. wide, course N. 40° E.; asc. 465 ft. over NE. slope.

38.71 Point for the 1/4 sec. cor. of secs. 1 and 12, at midpoint in departure on the S. bdy. of sec. 1; there is no remaining evidence of the original cor.

From this point, the 1/4 sec. cor. of secs. 1 and 12, erroneously established by Peterson and Berry in 1971, bears S. 23° 32' W., 0.20 chs. dist., monumented with an iron post, 2 1/2 ins. diam., firmly set, protruding 4 ins. above ground, with brass cap mkd. as described in the field notes of the resurvey.

Move the iron post to the corner point and

Reset the iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with brass cap mkd.

*FD. OK 5/99
BY E. FARR 1999-0103*

1/4 $\frac{S 1}{S 12}$
T 26 S R 8 W
1983
1971

from which a bearing tree mkd. by Peterson and Berry

A fir, 8 ins. diam., bears S. 20 1/4° E., 33 lks. dist., with healed blaze.

and a new bearing tree