

County Surveyor's Record, Douglas County, Oregon

16765

Dependent Resurvey, Portion, E. Bdy.,
Tps. 32 S., Rs. 4 and 5 W., Willamette Mer., Oregon

CHAINS

A fir, 19 ins. diam., bears N. $19\frac{1}{2}^{\circ}$ E., 12 $\frac{1}{2}$ lks. dist., mkd. N 1/16 S30 BT.

A fir, 10 ins. diam., bears S. $14\frac{1}{4}^{\circ}$ E., 38 $\frac{1}{2}$ lks. dist. mkd. N 1/16 S30 BT.

Ascend 40 ft. over SE. slope.

76.78

The remains of an original line tree; a sawed and decayed fir stump, 54 ins. diam., with hack mark visible on opened blaze, on N. face. This point now becomes an Angle Point.

N. $0^{\circ}04'$ E., beginning new measurement.

Ascend slightly over SE. slope.

0.50

Divide between Cow Creek and Starvout Creek, bears NE. and SW., also gravelled road, 20 lks wide, bears NE. curving E. and SW. curving S.; desc. 17 ft. along W. slope.

3.86

The cor. of secs. 24 and 25 only, perpetuated and recorded by R. L. Templin, Jr., Registered Engineer, No. 3024, in 1956, monumented with an iron pipe, 1 in. diam., firmly set, projecting 5 ins. above ground, from which the remains of the original bearing trees

A roothole, bears N. 53° E., 85 lks. dist.

A roothole, bears S. 41° E., 130 lks dist., alongside of which is lying a rotted madrone, 12 ins. diam., with healed double blaze.

A madrone, 12 ins. diam., bears N. 7° W., 58 lks. dist., with healed double blaze.

A madrone, 12 ins. diam., bears S. 11° W., 98 lks. dist., with decayed blaze.

and a bearing tree mkd. by Templin

A fir, 37 ins. diam., bears S. $0\frac{1}{2}^{\circ}$ W. 61 lks. dist., with scribe marks 02 visible on partially healed blaze.

and a bearing tree mkd. by J. M. Powell, Deputy County Surveyor, in 1970

A fir. 21 ins. diam., bears N. 11° W., 89 $\frac{1}{2}$ lks. dist., with healed double blaze.

At the corner point

Set an iron post, 28 ins. long, 2 $\frac{1}{2}$ ins. diam., 24 ins. in the ground, directly over the iron pipe, with brass cap mkd.

T 32 S
R 5 W R 4 W
S 24 | S 30
S 25 |
1979