

County Surveyor's Record, Douglas County, Oregon

16779

Dependent Resurvey, Portion of S. Bdy.,
(Fifth Standard Parallel South)
T. 22 S., R. 8 W., Willamette Meridian, Oregon

CHAINS

Set an iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with brass cap mkd.

T 22 S R 8 W
1/4 S 31
T 23 S R 8 W
1980

from which

A fir, 12 ins. diam., bears N. 4° E., 77 lks. dist., mkd. 1/4 S31 BT.

A fir, 15 ins. diam., bears N. 58 3/4° W., 119 1/2 lks. dist., mkd. X BT.

Asc. 10 ft. over rolling SE. slope.

47.65 Top of ascent, slopes S.; desc. 225 ft. over SW. slope.

57.75 Ravine, drains S. 10° W./ asc. 5 ft. over SE. slope.

62.60 Top of ascent, slopes S.; desc. 190 ft. over SW. slope.

68.95 Creek, 10 lks. wide, course S. 30° E.; asc. 100 ft. over NE. slope.

77.61 Point for the 80 1/16 sec. cor. of sec. 6 only, T. 23 S., R. 8 W., described in the field notes of the dependent resurvey of a portion of the subdivisional lines of T. 23 S., R. 8 W., executed concurrently under this same group.

Asc. 145 ft. over NE. slope.

85.90 The cor. of Tps. 22 S., Rs. 8 and 9 W., perpetuated and recorded by Milo E. Godfrey, Deputy County Surveyor, in 1963, monumented with an iron pipe, 1 1/2 ins. diam., firmly set, projecting 8 ins. above ground, from which the remains of an original bearing tree:

A roothole, bears N. 70° E., 137 lks. dist., alongside of which is a downed, decayed fir, 72 ins. diam., no marks visible.

and bearing tree mkd. by Godfrey

A fir, 13 ins. diam., bears N. 68° E., 69 1/2 lks. dist., with healed blaze.

A fir, 16 ins. diam., bears S. 89° W., 46 lks. dist., with healed blaze.

A fir, 26 ins. diam., bears N. 66° W., 38 lks. dist., with healed blaze.

At the corner point

Set an iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins in the ground, with brass cap mkd.

T 22 S
R 9 W | R 8 W
S 36 | S 31
T 23 S R 8 W S 6
1980

Deposit the iron pipe alongside the iron post.