

County Surveyor's Record, Douglas County, Oregon

16797

Dependent Resurvey, Portion of Subdivisional Lines,
T. 30 S., R. 7 W., Willamette Meridian, Oregon

CHAINS

38.58

The cor. of secs. 27, 28, 33, and 34, monumented with an iron post, 2 ins. diam., firmly set, projecting 8 ins. above ground, with brass cap mkd.

T 30 S	R 7 W
S 28	S 27
S 33	S 34
1918	

from which the remains of the original bearing trees

A pine, 36 ins. diam., bears S. 66° E., 65 lks. dist., with fragmentary scribe marks visible on burned blaze.

A pine, 48 ins. diam., bears N. 5° W., 118 lks. dist., with fragmentary scribe marks visible on open blaze. (Record, 140 lks.)

and the remains of a bearing tree mkd. by Sorrels in 1918

A pine snag, 32 ins. diam., bears N. 2 1/2° E., 126 lks. dist., with fragmentary scribe marks visible on open blaze.

and bearing trees mkd. by Vernon Tracy, Deputy County Surveyor in 1969

A cedar, 15 ins. diam., bears S. 74° E., 26 1/2 lks. dist., with fragmentary scribe marks visible on open blaze.

A pine, 20 ins. diam., bears S. 9° W., 25 1/2 lks. dist., with healed blaze.

Land, mountainous.
Soil, rocky clay loam.
Timber, fir, hemlock, cedar, maple, oak, madrone, alder, and chinquapin; undergrowth, salal, poison oak, vine maple, Oregon grape, rhododendron, ferns, and grasses.

From the cor. of secs. 22, 23, 26, and 27.

S. 88° 58' W., bet. secs. 22 and 27.

Ascend 140 ft. over SE. slope, through heavy timber and dense undergrowth.

9.15

Spur, slopes S.; continue over broken SW. slope changing to broken SE. slope.

14.80

Gravelled road, 30 lks. wide, bears N. 30° W. and S. 30° E.

19.885

Point for the E 1/16 sec. cor. of secs. 22 and 27.

Set an iron post, 28 ins. long 2 1/2 ins. diam., 24 ins. in the ground, with brass cap mkd.

E 1/16	S 22
	S 27
1980	

from which