

# County Surveyor's Record, Douglas County, Oregon

Subdivision of Section 23, T. 30 S., R. 4 W.  
Willamette Meridian, Oregon

16822

CHAINS

from which

A fir, 5 ins. diam., bears N. 73° E., 48 1/2 lks.  
dist., mkd. CS 1/16 S23 BT.

A fir, 15 ins. diam., bears N. 79° W., 62 lks.  
dist., mkd. CS 1/16 S23 BT.

Descend 125 ft. over NW. slope, changing to NE. slope.

38.12 Point for the center 1/4 sec. cor. of sec. 23, at inter-  
section with the E. and W. center line.

Set an iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins.  
in the ground, with brass cap mkd.

T 30 S R 4 W  
C 1/4 S 23  
1981

FD. OK 10-93 R. BROWN  
M119-7

from which

A fir, 24 ins. diam., bears N. 60° E., 45 1/2 lks.  
dist., mkd. C 1/4 S23 BT.

A black oak, 28 ins. diam., bears S. 1/2° W., 25 lks.  
dist., mkd. C 1/4 S23 BT.

Descend 35 ft. over broken NE. slope.

39.25 Gravelled road, 15 lks. wide, bears N. 40° W. and  
S. 70° E.

66.50 Left bank of South Umpqua River, bears N. 45° W. and  
S. 45° E., course N.45° W.

71.40 Right bank of South Umpqua River, bears N. 55° W. and  
S. 45° E.; asc. 15 ft. over SE. slope.

74.20 South Umpqua Highway, asphalt surfaced, 50 lks. wide,  
bears N. 75° W. and S. 75° E.

74.90 Woven wire fence, extends N. 60° E. and S. 35° E.

76.80 Hammon Creek, 2 lks. wide, course S. 45° W.; asc. 45 ft.  
over SE. slope.

77.84 The 1/4 sec. cor. of secs. 14 and 23, perpetuated and re-  
corded by James W. Byron, Deputy County Surveyor, in 1963,  
determined at record bearing and distance from the remain-  
ing original bearing tree:

A white oak, 22 ins. diam., bears S. 45° W., 36 lks.  
dist. with illegible scribe marks visible on  
partially healed blaze.

and the remains of a bearing tree mkd. by Byron

A root hole, bears N. 86° E., 35 lks. dist., with  
a down oak alongside, 12 ins. diam., with  
a healed blaze.

At the corner point

Set an iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins.  
in the ground, with brass cap mkd.