

County Surveyor's Record, Douglas County, Oregon

Subdivision of Section 23, T. 30 S., R. 4 W., **16824**
Willamette Meridian, Oregon

CHAINS	
80.52	The 1/4 sec. cor. of secs. 22 and 23.
	<p>From the S 1/16 sec. cor. of secs. 23 and 24.</p> <p>N. 89° 59' W., on the E. and W. center line of the SE 1/4 of sec. 23.</p> <p>Descend 50 ft. over broken SW. slope, through heavy timber and dense undergrowth.</p>
0.60	Woven wire fence, extends N. 10° W. and S. 10° E.
0.90	Gravelled driveway, 15 lks. wide, bears N. 10° W. and S. 10° E.
2.20	South Umpqua Highway, asphalt surfaced, 50 lks. wide, bears N. 25° W. and S. 25° E.
5.05	Right bank of South Umpqua River, bears N. 10° E. and S. 10° W., course N. 10° E.
7.60	Left bank of South Umpqua River, bears N. 10° W. and S. 10° E.; asc. 450 ft. over NE. slope.
8.25	Barbed wire fence, extends N. 15° W. and S. 15° E.
9.30	Gravelled road, 15 lks. wide, bears N. 20° W. and S. 20° E.
19.65	Spur, slopes N. 30° E.; desc. 250 ft. over broken NW. slope.
33.30	Spring, drains N. 30° W.; asc. 15 ft. over NE slope.
36.05	Spur, slopes N. 15° W.; desc. 40 ft. over NW slope.
40.09	The center S 1/16 sec. cor. of sec. 23.
	<p>From the center S 1/16 sec. cor. of sec. 23.</p> <p>N. 89° 58' W., on the E. and W. center line of the SW 1/4 of sec. 23.</p> <p>Descend 50 ft. over broken NW. slope, through heavy timber and dense undergrowth.</p>
0.35	Woven wire fence, extends N. and S.
12.90	Barbed wire fence, extends N. 15° W. and S. 15° E., enter pasture.
33.85	Barbed wire fence, extends N. 5° E. and S. 5° W., enter scattering timber and moderate undergrowth.
34.00	Creek, 2 lks. wide, course N. 5° E.; asc. 35 ft. over NE slope.
40.25	The S 1/16 sec. cor. of secs. 22 and 23.
	<p>GENERAL DESCRIPTION</p> <p>The lands included in the foregoing resurvey are located along the South Umpqua River, near the small community of Days Creek, Oregon. The elevation ranges</p>