

# County Surveyor's Record, Douglas County, Oregon

16332

Dependent Resurvey, Portion of Subdivisional Lines,  
T. 23 S., R. 8 W., Willamette Meridian, Oregon

**CHAINS**

- A decayed fir stump, 38 ins. diam., bears N. 1° E., 24 lks. dist., with old axe marks visible on decayed bark blaze. (Record and to face, 22 lks.)
- A roothole, bears S. 31° W., 30 lks. dist., alongside of which is a downed, decayed fir, size indeterminate, no marks remaining.
- A decayed fir stump, size indeterminate, bears N. 79° W., 48 lks. dist., no marks remaining.

and the remains of bearing trees mkd. by Tracy.

- A cedar, 22 ins. diam., bears N. 45° E., 27 lks. dist., with scribe mark 8 visible on partially healed blaze.
- A fir, 19 ins. diam., bears S. 75° E., 22 1/2 lks. dist., with healed blaze.
- A hemlock, 20 ins. diam., bears S. 11° W., 21 lks. dist. with fragmentary scribe marks visible on partially healed blaze.
- A roothole, bears N. 56° W., 26 lks. dist., alongside of which is a downed fir, 14 ins. diam., no marks visible.

At the corner point

Set an iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with brass cap mkd.

T 23 S R 8 W  
S 6 | S 5  
S 7 | S 8  
1980

FD OK  
C. MUIKINS  
12/95 M 123-32

from which a new bearing tree

- A fir, 26 ins. diam., bears N. 69 3/4° W., 44 lks. dist., mkd. T23S R8W S6 BT.

Deposit iron capped iron post alongside iron post.

Land, mountainous.  
Soil, rocky clay.  
Timber, fir, cedar, hemlock, alder, and maple;  
undergrowth, vine maple, rhododendron, salmonberry,  
huckleberry, salal, fern, and wild rose.

N. 89° 17' W., bet. secs. 6 and 7.

Desc. 20 ft. over SE. slope, through moderate timber and undergrowth.

- 2.70 Ravine, drains S. 20° W.; asc. 25 ft. over SE. slope.
- 4.95 Spur, slopes S. 20° W.; desc. 45 ft. over SW. slope.
- 7.45 Ravine, drains S. 30° W.; asc. 10 ft. over SE. slope.
- 10.60 Top of ascent, slopes S.; desc. 40 ft. over SW. slope.
- 13.45 Creek, 1 lk. wide, course S. 5° W.; asc. 15 ft. over SE. slope.