

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Portion of Subdivisional Lines, 16886
T. 29 S., R. 3 W., Willamette Mer., Oregon

CHAINS	
	<p>Land, mountainous. Soil, clay loam. Timber, yew, oak, fir, hemlock, cedar, willow, ash, alder, pine, maple, and madrone; undergrowth, poison oak, arrowwood, hazel, thimbleberry, blackberry, fern, elderberry, and young timber.</p>
	<p>N. 0° 18' E., bet. secs. 16 and 17.</p> <p>Ascend 135 ft. over broken SW. slope, through open field.</p>
16.00	<p>Ridge, bears N. 60° W. and S. 40° E.; desc. 30 ft. over NE. slope.</p>
20.095	<p>Point for the S 1/16 sec. cor. of secs. 16 and 17.</p> <p>Set an iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with brass cap mkd.</p> <p style="text-align: center;">S 1/16 S 17 S 16 1980</p> <p>from which</p> <p style="padding-left: 40px;">A fir, 8 ins. diam., bears S. 36° E., 12 1/2 lks. dist., mkd. S 1/16 S16 BT.</p> <p style="padding-left: 40px;">A fir, 10 ins. diam., bears N. 57° W., 39 1/2 lks. dist., mkd. S 1/16 S17 BT.</p>
21.40	<p>Descend 20 ft. over NE. slope.</p> <p>Head of ravine, drains S. 50° E.; asc. 95 ft. over SE. slope.</p>
32.15	<p>Dirt road, 15 lks. wide, bears NE. and SW.</p>
40.19	<p>Point for the 1/4 sec. cor. of secs. 16 and 17, at proportionate distance; there is no remaining evidence of the original corner.</p> <p>Set an iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with brass cap mkd.</p> <p style="text-align: center;">T 29 S R 3 W 1/4 S 17 S 16 1980</p> <p>from which</p> <p style="padding-left: 40px;">A pine, 18 ins. diam., bears N. 25 1/2° E., 21 1/2 lks. dist., mkd. 1/4 S16 BT.</p> <p style="padding-left: 40px;">A fir, 22 ins. diam., bears S. 86° W., 71 1/2 lks. dist., mkd. 1/4 S17 BT.</p>
60.70	<p>Ascend 45 ft. over broken SE. slope.</p> <p>Spur, slopes S. 20° W.; asc. 185 ft. over broken SW. slope.</p>