

County Surveyor's Record, Douglas County, Oregon

16888

Dependent Resurvey, Portion of Subdivisional Lines,
T. 29 S., R. 3 W., Willamette Mer., Oregon

CHAINS	
	<p>A madrone, 15 ins. diam., bears N. 66° E., 76 1/2 lks. dist., with fragmentary scribe marks visible on partially healed blaze.</p> <p>A madrone, 19 ins. diam., bears S. 45° E., 14 lks. dist., with fragmentary scribe marks visible on partially healed blaze.</p> <p>A fir, 25 ins. diam., bears N. 35° W., 17 1/2 lks. dist., with healed blaze.</p> <p>Cor. is located on a spur, slopes E.</p> <p>N. 3° 47' E., bet. secs. 4 and 5.</p> <p>Descend 295 ft. over broken N. slope, through heavy timber and dense undergrowth</p>
10.35	Ravine, drains N. 40° E.; asc. 5 ft. over SE. slope.
14.85	Spur, slopes N. 60° E.; desc. 45 ft. over NE. slope.
16.30	Ravine, drains E.; asc. 45 ft. over SE. slope.
19.30	Spur, slopes E.; desc. 5 ft. over NE. slope
24.60	Ravine, drains N. 85° E.; asc. 35 ft. over SE. slope.
29.60	Spur, slopes S. 80° E.; desc. 160 ft. over NE. slope.
34.60	Creek, 1 lk. wide, course S. 50° E.; asc. 40 ft. over SE. slope.
39.08	<p>Point for the 1/4 sec. cor. of secs. 4 and 5, at proportionate distance; there is no remaining evidence of the original corner.</p> <p>Set an iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with brass cap mkd.</p> <p style="text-align: center;">T 29 S R 3 W 1/4 S 5 S 4 1980</p> <p>from which</p> <p>A yew, 10 ins. diam., bears S. 68° E., 26 lks. dist., mkd. 1/4 S4 BT.</p> <p>A fir, 6 ins. diam., bears S. 47° W., 27 1/2 lks. dist., mkd. 1/4 S5 BT.</p> <p>Ascend 10 ft. over SE. slope.</p>
40.90	Spur, slopes S. 60° E.; desc. 50 ft. over NE. slope.
42.65	Creek, 1 lk. wide, course E.; asc. 225 ft. over SE. slope.
50.50	Spur, slopes S. 65° E.; desc. 140 ft. over NE. slope.
58.62	<p>Point for the N 1/16 sec. cor. of secs. 4 and 5.</p> <p>Set an iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with brass cap mkd.</p>