

County Surveyor's Record, Douglas County, Oregon

16891

Dependent Resurvey, Portion of Subdivisional Lines,
T. 29 S., R. 3 W., Willamette Mer., Oregon

CHAINS

Reset iron pipe alongside iron post.

Land, mountainous.

Soil, rocky clay.

Timber, yew, cedar, maple, madrone, oak, fir, hemlock, and alder; undergrowth, hazel, poison oak, arrowwood, fern, vine maple, blackberry, thimbleberry, and young timber.

From the 1/4 sec. cor. of secs. 19 and 20, perpetuated and recorded by Ben Irving, Deputy County Surveyor, in 1931, monumented with an iron pipe, 2 ins. diam., firmly set, projecting 2 ins. above ground, from which a bearing tree mkd. by Irving

An oak, 10 ins. diam., bears N. 3° E., 233 lks. dist., with healed blaze.

At the corner point

Set an iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with brass cap mkd.

T 29 S R 3 W

1/4

S 19 | S 20

1980

from which a new bearing tree

A cedar, 18 ins. diam., bears N. 36 1/2° W., 64 lks. dist., mkd. 1/4 S19 BT.

Reset the iron pipe alongside the iron post.

N. 0° 13' W., bet. secs. 19 and 20.

Ascend 100 ft. over SW. slope, through scattering timber and dense undergrowth.

6.48

Intersect the N. bdy. of Donation Land Claim No. 37, and point for the crossing closing corner.

Set an iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with brass cap mkd.

CCC

S 19 | S 20
DLC 37

1980

from which

A fir, 6 ins. diam., bears N. 66 1/2° E., 37 1/2 lks. dist., mkd. T29S R3W S20 CCC BT.

A fir, 11 ins. diam., bears N. 63° W., 56 1/2 lks. dist., mkd. T29S R3W S19 CCC BT.

From this point, the NE. cor. of Donation Land Claim No. 37, bears S. 89° 54' E., 29.065 chs. dist., herein-after described.

Ascend 100 ft. over broken SW. slope.