

County Surveyor's Record, Douglas County, Oregon

16923

Subdivision of Section 3,
T. 27 S., R. 2 W., Willamette Meridian, Oregon

| CHAINS | |
|--------|---|
| | <p style="text-align: center;">A cedar, 12 ins. diam., bears S. 34° E., 87 lks. dist., with healed blaze.</p> <p>and a bearing tree mkd. by Tracy</p> <p style="text-align: center;">A fir, 16 ins. diam., bears S. 71° W., 8 lks. dist., with healed blaze.</p> <p>Cor. is located in a creek, 1 lk. wide, course S. 20° W. N. 87° 02' W., on the E. and W. center line of sec. 3.</p> <p>Ascend 90 ft. over broken SE. slope, through light timber and dense undergrowth.</p> |
| 18.95 | Spur, slopes S.; desc. 40 ft. over SW. slope. |
| 22.00 | Creek, 3 lks. wide, course S.; asc. 95 ft. over broken SE. slope. |
| 25.10 | Spur, slopes S.; desc. 95 ft. over SW. slope. |
| 32.80 | Ravine, drains S.; asc. 10 ft. over SE. slope. |
| 40.16 | The center 1/4 sec. cor. of sec. 3. |
| | Ascend 20 ft. over SE. slope. |
| 44.00 | Spur, slopes S.; desc. 80 ft. over SW slope. |
| 49.10 | Creek, 10 lks. wide, course S.; asc. 210 ft. over SE. slope. |
| 60.22 | Point for the center W 1/16 sec. cor. of sec. 3. |
| | Set an iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with brass cap mkd. |
| | $C \frac{W \ 1/16}{S \ 3} C$ <p>1979</p> |
| | from which |
| | <p>A cedar, 9 ins. diam., bears N. 70° E., 34 lks. dist., mkd. C W 1/16 S3 BT.</p> <p>A fir, 14 ins., diam., bears N. 19 1/2° W., 20 1/2 lks. dist., mkd. C W 1/16 S3 BT.</p> |
| | Ascend 100 ft. over SE. slope. |
| 65.30 | Spur, slopes S. 10° W.; desc. 100 ft. over SW. slope. |
| 76.90 | Ravine, drains S. 20° W.; asc. 30 ft. over SE. slope. |
| 80.28 | The 1/4 sec. cor. of secs. 3 and 4, monumented with an iron post, 2 1/2 ins. diam., firmly set, projecting 10 ins. above the ground, in a mound of stone, 2 ft. base to top, with brass cap mkd. |
| | $\begin{array}{c} T \ 27 \ S \ R \ 2 \ W \\ \\ 1/4 \\ \\ S \ 4 \ \ S \ 3 \\ \\ 1957 \end{array}$ |