

# County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey of a Portion of the  
Subdivisional Lines, T. 26 S., R. 2 W.,  
Willamette Meridian, Oregon

16942

**CHAINS**

and bearing trees mkd. by Tracy

A hemlock, 10 ins. diam., bears S. 43° W., 12 lks. dist., with illegible scribe marks visible on partially healed blaze.

A hemlock, 10 ins. diam., bears N. 67° W., 15 lks. dist., with illegible scribe marks visible on partially healed blaze.

No other suitable bearing trees available.

Cor. is located on W. edge of logged area, edge bears N. and S.

Land, mountainous.

Soil, rocky clay.

Timber, fir, yew, cedar, hemlock, alder, oak, maple, ash, pine, and madrone; undergrowth, poison oak, vine maple, fern, arrowwood, hazel, salal, salmonberry, blackberry, wild rose, Oregon grape, and young timber.

Subdivision of Section 9  
T. 26 S., R. 2 W., Willamette Meridian, Oregon

From the 1/4 sec. cor. of secs. 9 and 16, monumented with an iron post, 1 ins. diam., firmly set, projecting 10 ins. above ground, with brass cap mkd.

1/4  $\frac{S \ 9}{S \ 16}$   
1918

*FD. OK BY  
D. EDWARDS 1/2000 M/3A-15*

from which the remains of the original bearing trees

A roothole, bears N. 67 1/4° E., 23 lks. dist., alongside of which is a cedar, 10 ins. diam., no marks visible.

A roothole, bears S. 57 1/4° E., 27 lks. dist., alongside of which is a cedar, 16 ins. diam., no marks visible.

and the remains of bearing trees mkd. by Zirpel and Glenn

A fir snag, 9 ins. diam., bears N. 16 1/2° E., 31 lks. dist., with scribe marks 1/4 S9 BT on open blaze.

A roothole, bears S. 33 3/4° E., 110 lks. dist., with downed fir alongside, 9 ins. diam., no marks visible.

and new bearing trees

A fir, 16 ins. diam., bears N. 48 1/2° E., 81 lks. dist., mkd. 1/4 S9 BT.

An oak, 8 ins. diam., bears S. 1 1/2° E., 55 lks. dist., mkd. 1/4 S16 BT.

N. 1° 32' E., on the N. and S. center line of sec. 9.

Descend 70 ft. over NW. slope, through heavy timber and dense undergrowth.