

County Surveyor's Record, Douglas County, Oregon

16979

Dependent Resurvey, Portion of Subdivisional Lines,
T. 32 S., R. 6 W., Willamette Meridian, Oregon

CHAINS	
71.90	Creek, 2 lks. wide, course S. 60° E.; asc. 170 ft. over E. slope.
80.42	The cor. of secs. 11, 12, 13, and 14. Land, Mountainous. Soil, rocky clay. Timber, fir, pine, cedar, oak, madrone, maple, alder, and chinquapin; undergrowth, poison oak, manzanita, hazel, vine maple, salal, Oregon grape, and young timber.
	North, bet. secs. 11 and 12. Descend 10 ft. along E. slope, through heavy timber and dense undergrowth.
1.15	Creek, 6 lks. wide, course N. 80° E.; asc. 100 ft. over SE. slope.
10.65	Spur, slopes E.; desc. 95 ft. over NE. slope.
15.50	Creek, 1 lk. wide, course E.; asc. 190 ft. over broken SE. slope.
21.55	Dirt road, 20 lks. wide, bears N. 20° E. and S. 60° W., in curve.
32.85	Spur, slopes E.; desc. 115 ft. over NE. slope.
37.15	Ravine, drains E.; asc. 50 ft. over SE. slope.
39.92	Point for the 1/4 sec. cor. of secs. 11 and 12, at proportionate distance; there is no remaining evidence of the original corner. Set an iron post, 28 ins. long, 2 1/2 ins. diam., 21 ins. in the ground, with brass cap mkd. <div style="text-align: center;"> T 32 S R 6 W 1/4 S 11 S 12 1980 </div> from which <div style="margin-left: 40px;"> A fir, 11 ins. diam., bears S. 33 1/2° E.; 30 lks. dist., mkd. 1/4 S12 BT. A fir, 11 ins. diam., bears N. 46° W.; 12 1/2 lks. dist., mkd. 1/4 S11 BT. </div> Ascend 300 ft. over broken SE. slope.
61.20	Spur, slopes E.; desc. 30 ft. over NE. slope.
63.35	Ravine, drains E.; asc. 380 ft. over SE. slope.
79.84	Point for the cor. of secs. 1, 2, 11, and 12, at proportionate distance; there is no remaining evidence of the original corner. Set an iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with brass cap mkd. <div style="text-align: center;"> T 32 S R 6 W S 2 S 1 S 11 S 12 1980 </div>