

County Surveyor's Record, Douglas County, Oregon

16981

Dependent Resurvey, Portion of Subdivisional Lines,
T. 32 S., R. 6 W., Willamette Meridian, Oregon

CHAINS	
	<p>A cedar, 30 ins. diam., bears N. 67° W., 41 1/2 lks. dist., with scribe marks T32S R6W S1 BT RE 2311 visible on partially healed blaze.</p> <p>and a new bearing tree</p> <p>A fir, 6 ins. diam., bears N. 50° E., 9 1/2 lks. dist., mkd. T32S R6W S6 BT.</p> <p>S. 89° 03' W., bet. secs. 1 and 12.</p> <p>Ascend 165 ft. over E. slope, through heavy timber and dense undergrowth.</p>
6.10	Bear Ridge, bears N. and S.; desc. 855 ft. over W. slope.
40.08	<p>Point for the 1/4 sec. cor. of secs. 1 and 12, at proportionate distance; there is no remaining evidence of the original corner.</p> <p>Set an iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with brass cap mkd.</p> <div style="text-align: center; margin: 10px 0;"> <p>T 32 S R 6 W</p> <p>1/4 $\frac{S 1}{S 12}$</p> <p>1980</p> </div> <p>from which</p> <p>A cedar, 9 ins. diam., bears S. 33 3/4° W., 22 lks. dist., mkd. 1/4 S12 BT.</p> <p>A fir, 19 ins. diam., bears N. 1° W., 71 lks. dist., mkd. 1/4 S1 BT.</p> <p>Descend 20 ft. over W. slope.</p>
41.35	Bear Creek, 6 lks. wide, course S. 15° W.; asc. 245 ft. over SE. slope.
51.40	Spur, slopes SE.; desc. 65 ft. over SW. slope.
59.25	Ravine, drains SE.; asc. 475 ft. over broken SE. slope.
80.16	<p>The cor. of secs. 1, 2, 11, and 12.</p> <p>Land, mountainous. Soil, rocky clay. Timber, fir, pine, cedar, oak, madrone, hemlock, and alder; undergrowth, poison oak, manaanita, hazel, vine maple, salal, and Oregon grape.</p>
	<p>North, bet secs. 1 and 2.</p> <p>Ascend 140 ft. over SE. slope. through heavy timber and dense undergrowth.</p>
7.70	Dirt road, 15 lks. wide, bears N. 20° E. and S. 20° W.
8.20	Buck Ridge, bears N. 20° E. and S. 20° W.; desc. 195 ft. over broken NW. slope.
36.20	Ravine, drains W.; desc. 60 ft. along W. slope.