

# County Surveyor's Record, Douglas County, Oregon

16982

Dependent Resurvey, Portion of Subdivisional Lines,  
T. 32 S., R. 6 W., Willamette Meridian, Oregon

**CHAINS**

39.92

Point for the 1/4 sec. cor. of secs. 1 and 2, at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with brass cap mkd.

T 32 S R 6 W  
          1/4  
S 2 | S 1  
      1980

from which

A fir, 15 ins. diam., bears S. 63° E., 26 lks. dist., mkd. 1/4 S1 BT.

A fir, 10 ins. diam., bears N. 21 1/2° W., 19 lks. dist., mkd. 1/4 S2 BT.

Descend 70 ft. along broken W. slope.

50.00

Lawson Creek, 4 lks. wide, course S. 15° W.; asc. 575 ft. over SW. slope.

69.20

Dirt road, 20 lks. wide, bears N. 80° E. and S. 80° W.

72.50

Ridge, bears E. and W.; desc. 170 ft. over NE. slope.

77.15

The cor. of secs. 1, 2, 35, and 36, on the N. bdy. of the Tp., perpetuated and recorded by James W. Byron, Deputy County Surveyor, in 1963, monumented with an iron rod, 3/4 in. diam., firmly set, projecting 4 ins. above ground, from which the remains of the original bearing trees:

A root hole, bears S. 53° E., 50 lks. dist., with a down fir alongside, 12 ins. diam., with healed blaze.

A fir, 30 ins. diam., bears N. 30° W., 59 lks. dist., with healed blaze.

and bearing trees mkd. by Byron

A cedar, 9 ins. diam., bears N. 84 3/4° E., 67 lks. dist., with scribe marks S36 T31S R6W CS BT visible on open blaze.

A hemlock, 16 ins. diam., bears S. 12° E., 5 lks. dist., with healed blaze.

A hemlock, 18 ins. diam., bears N. 80° W., 77 lks. dist., with scribe marks S35 T31S R6W CS BT visible on partially healed blaze.

At the corner point

Set an iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, directly over iron rod, with brass cap mkd.

T 31 S R 6 W  
S 35 | S 36  
S 2 | S 1  
T 32 S  
      1980