

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Portion of Subdivisional Lines,
T. 29 S., R. 8 W., Willamette Meridian, Oregon

17002

CHAINS

W 1/16 $\frac{S\ 9}{S\ 16}$
1980

*Corner Report
OSHO - 2/11/06
CS 63/9*

from which

A fir, 4 ins. diam., bears N. 83 1/4° W., 9 1/2 lks. dist., mkd. X BT.

A fir, 7 ins. diam., bears S. 88 1/2° E., 20 lks. dist., mkd. W 1/16 S16 BT.

From this point, a car axle, 1 in. diam., firmly set, projecting 10 ins. above ground, not of known record, bears N. 8° E., 22 1/2 lks. dist.

Ascend 10 ft. over NE. slope.

20.90 Three-wire transmission power line, bears N. 35° E. and S. 35° W.

23.40 Top of ascent, slopes N.; desc. 10 ft. over E. slope.

35.30 Ridge, bears N. 5° E. and S. 5° W.; desc. 30 ft. over broken SW. slope.

39.97 The cor. of secs. 8, 9, 16, and 17, perpetuated and recorded by Ben B. Irving, Deputy Douglas County Surveyor, in 1938, and further perpetuated and recorded by James W. Byron, Deputy Douglas County Surveyor, in 1958, monumented with an iron post, 1 1/4 ins. diam., firmly set, projecting 10 ins. above ground, with brass cap mkd.

COUNTY SURVEYORS OFFICE
T 29 S R 8 W
S 8 | S 9

S 17 | S 16
1958

*FD OK
M. Smalley
8/95 M119 D69*

from which the remains of an original bearing tree

A fir, 38 ins. diam., bears N. 20° W., 46 lks. dist., with fragmentary scribe marks visible on bark blaze.

and a bearing tree mkd. by Irving

A root hole, bears S. 40° E., 44 lks. dist., with a down fir alongside, 10 ins. diam., with axe marks visible on open blaze.

and bearing trees mkd. by Byron

A cedar, 20 ins. diam., bears N. 86° E., 119 lks. dist., with fragmentary scribe marks visible on open blaze.

A fir, 15 ins. diam., bears S. 55° E., 72 lks. dist., with healed blaze.

A fir, 13 ins. diam., bears S. 71° W., 71 1/2 lks. dist., with healed blaze.

A cedar, 27 ins. diam., bears N. 10° W., 91 lks. dist., with healed blaze.