

County Surveyor's Record, Douglas County, Oregon

17025

Subdivision of Sec. 15,
T. 29 S., R. 8 W., Willamette Meridian, Oregon

CHAINS	
1.55	Spur, slopes S. 20° W.; desc. 35 ft. over SW. slope.
8.15	Creek, 5 lks. wide, course SE.; asc. 150 ft. over broken NE. slope.
19.78	The SE 1/16 sec. cor. of sec. 15. Ascend 100 ft. over broken NE. slope.
39.66	The center S 1/16 sec. cor. of sec. 15.
<p>From the center N 1/16 sec. cor. of sec. 15.</p> <p>S. 89° 43' W., on the E. and W. center line of the NW 1/4 of sec. 15.</p> <p>Ascend 310 ft. over SE. slope, through heavy timber and dense undergrowth.</p>	
10.75	Spur, slopes SW.; desc. 280 ft. over SW. slope.
39.72	The N 1/16 sec. cor. of secs. 15 and 16.
<p>GENERAL DESCRIPTION</p> <p>The lands included in the foregoing survey are located approximately 2 miles northeasterly from Camas Valley, Oregon. The area is drained by Berry Creek and Shields Creek, with a number of other small drainages. The elevations range from about 900 feet above sea level near the 1/4 section corner of sections 2 and 11, to about 2,000 feet above sea level near the 1/4 section corner of sections 10 and 15.</p> <p>Access into the area is via Oregon State Highway No. 42, and a number of gravelled and dirt roads extending from it into the area.</p> <p>Timber in the area consists of fir, hemlock, maple, oak, cedar, madrone, myrtle, yew, and chinquapin, with undergrowth of salal, poison oak, vine maple, Oregon grape, ferns, manzanita, rhododendron, blackberry, huckleberry, salmonberry, thimbleberry, arrowwood, hazel, and young timber.</p> <p>The soil is composed of a rocky clay, with some scattered rock outcrops.</p> <p>No evidence of minerals was noted in the area covered by this survey.</p> <p>The average of a considerable number of readings over all parts of the area gives a value of 19° 30' E., for the mean magnetic declination. There is a range of up to 2° in local attraction.</p>	