

# County Surveyor's Record, Douglas County, Oregon

**17042**

Dependent Resurvey, Portion of N. Bdy.,  
T. 27 S., R. 8 W., Willamette Meridian, Oregon

CHAINS	
	<p>and a new bearing tree</p> <p style="padding-left: 40px;">A fir, 13 ins. diam., bears S. 66 1/2° E., 22 lks. dist., mkd. T27S R8W S2 BT.</p> <p>S. 89° 54' W., bet. secs. 3 and 34, marking and blazing the true line.</p> <p>Descend 435 ft. over SW. slope, through moderate timber and undergrowth.</p>
21.45	Panther Creek, 10 lks. wide, course N. 35° W.; asc. 205 ft. over NE. slope.
27.15	Spur, slopes N. 20° W., desc. 225 ft. over NW. slope.
40.56	<p>The cor. of secs. 3, 4, 33, and 34, reestablished at proportionate dist. and recorded by Bruce A. Shaner, Registered Professional Engineer No. 4906, in 1974, and accepted as the best available evidence of the position of the original corner, monumented with a PK nail driven flush with the surface and 10 ft. above the base of a nearly vertical rock slope, from which a witness cor. and bearing trees mkd. by Shaner</p> <p style="padding-left: 40px;">An iron post, 1 1/2 ins. diam., firmly set, projecting 4 ins. above ground, bears N. 0° 11' E., 0.046 chs. dist., with brass cap mkd. WITNESS CORNER SOUTH 3 FT TO T26S S3 S4 S33 S34 T27S R8W 1974.</p> <p style="padding-left: 40px;">A cedar, 14 ins. diam., bears N. 13° E., 27 lks. dist., with scribe marks T26S R8W S34 BT visible on partially healed blaze.</p> <p style="padding-left: 40px;">A fir, 18 ins. diam., bears S. 5° E., 39 lks. dist., with healed blaze.</p> <p style="padding-left: 40px;">A fir, 20 ins. diam., bears S. 20° W., 50 lks. dist., with healed blaze.</p> <p style="padding-left: 40px;">A fir, 28 ins. diam., bears N. 48° W., 162 1/2 lks. dist., with healed blaze.</p> <p>Land, mountainous. Soil, rocky clay loam. Timber, fir, cedar, hemlock, alder, madrone, maple, and yew; undergrowth, vine maple, Oregon grape, ocean spray, rhododendron, poison oak, salal, and fern.</p>
	<p>S. 89° 54' W., bet. secs. 4 and 33.</p> <p>Descend 20 ft. over NW. slope, through moderate timber and undergrowth.</p>
1.70	Panther Creek, 20 lks. wide, course S. 40° W.; asc. 60 ft. over SE. slope.
4.00	Spur, slopes S.; desc. 65 ft. over SW. slope.
8.25	Panther Creek, 25 lks. wide, course S. 50° W. from a course of N. 70° W.; asc. 130 ft. over broken SE. slope.
13.80	Spur, slopes S. 10° E.; desc. 85 ft. over SW. slope.
21.95	Creek, 10 lks. wide, course S. 40° E.; asc. 715 ft. over SE. slope.