

County Surveyor's Record, Douglas County, Oregon

17062

Dependent Resurvey, Portion of E. Bdy.,
T. 22 S., R. 13 W., Willamette Meridian, Oregon

CHAINS

bears S. 11° 41' E., 8.96 chs. dist., and the point adjacent to the highway reference point bears N. 11° 41' W., 29.50 chs. dist. The highway reference point at station 363+14.97 is a steel rod, 1/2 in. diam., set 1 in. below the ground surface.

Continue descent over broken NW. slope.

17.675

U.S. Highway No. 101, asphalt surfaced, 60 lks. wide, bears N. 11° 41' W. and S. 11° 41' E.

40.22

The 1/4 sec. cor. of secs. 25 and 30, monumented with an iron pipe, 3/4 in. diam., firmly set flush with the ground. This monument was reported by Vernon R. Tracy in 1973, as described in a Douglas County Surveyor's record, and is accepted as the best available evidence of the original cor. from which bearing trees mkd. by person(s) unknown

A fir snag, 6 ins. diam., bears N. 57° 3/4° E., 32 lks. dist., with scribe marks S30 T22 R12 O visible on an open blaze.

A pine, 20 ins. diam., bears N. 30 3/4° W., 87 lks. dist., with scribe marks 1/4 S25 T22S R13W CS visible on a partially healed blaze.

At the corner point

Set an iron post, 28 ins. long, 2 1/2 ins. diam., 25 ins. in the ground, with brass cap mkd.

T 22 S	FD. OK 11-92	J. MINOR
1/4		
R 13 W		R 12 W
S 25		S 30
1982		

*FD. OK 11-92 J. MINOR
M 116-11*

and a new bearing tree

A fir, 10 ins. diam., bears N. 43° E., 41 lks. dist., mkd. 1/4 S30 BT.

Deposit the local iron pipe inside the iron post.

Dependent Resurvey of a Portion of the
Subdivisional Lines, T. 22 S., R. 13 W.,
Willamette Meridian, Oregon

(Restoring the survey by Harvey Gordon in 1857)

From the standard cor. of secs. 1, 2, 35, and 36, monumented with an aluminum rod, 5/8 in. diam., firmly set in concrete, projecting 6 ins. above the ground, with aluminum cap mkd.

S C	
T 22 S	R 13 W
S 35	S 36
S 2	S 1
T 23 S	
1980	

from which bearing trees mkd. by Goodson, Lee, and Tawney