

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Portion of Subdivisional Lines,
T. 22 S., R. 13 W., Willamette Meridian, Oregon

17063

CHAINS

A spruce, 10 ins. diam., bears S. 11 1/2° E., 793 lks. dist., with scribe marks T23S R13W S1 SC BT visible on a partially healed blaze.

A pine, 12 ins. diam., bears S. 11° W., 1026 lks. dist., with scribe marks T23S R13W S2 SC BT visible on a partially healed blaze.

No other suitable trees available within limits.

N. 0° 15' W., bet. secs. 35 and 36, marking the true line.

Over nearly level rolling sand dunes, through widely scattering timber and undergrowth.

39.79

Point for the 1/4 sec. cor. of secs. 35 and 36, a proportionate distance; there is no remaining evidence of the original corner.

Set an aluminum rod, 22 ft. long, 5/8 in. diam., 21 ft. in the ground, in concrete, with aluminum cap mkd.

T 22 S	R 13 W
1/4	
S 35	S 36
1982	

from which

A spruce, 12 ins. diam., bears N. 30 1/2° W., 234 lks. dist., mkd. 1/4 S35 BT.

No suitable tree available within limits in sec. 36.

Set a steel fence post alongside the aluminum rod.

Descend 45 ft. over rolling sand dunes.

79.58

Point for the cor. of secs. 25, 26, 35, and 36, at proportionate position. There is no remaining evidence of the original corner.

Set an aluminum rod, 6 ft. long, 5/8 in. diam., 5 ft. in the ground, in concrete, with aluminum cap mkd.

T 22 S	R 13 W
S 26	S 25
S 35	S 36
1982	

from which

A pine, 10 ins. diam., bears S. 76 1/4° W., 551 lks. dist., mkd. T22S R13W S35 BT.

A spruce, 19 ins. diam., bears N. 80° W., 863 lks. dist., mkd. T22S R13W S26 BT.

No suitable trees available within limits in secs. 25 and 36.

Set a steel fence post alongside the aluminum rod.

From this point, the cor. of secs. 13, 14, 23, and 24, bears N. 0° 22' W., 159.18 chs. dist., hereinafter described.