

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Portion of Subdivisional Lines,
T. 22 S., R. 13 W., Willamette Meridian, Oregon

17064

CHAINS

This control line was fully retraced and careful search was made for evidence of intervening corners, none of which were recovered.

Land, rolling dunes.
Soil, sand.
Timber, spruce, pine, and fir; undergrowth, salal, huckleberry, willow, and young timber.

From the cor. of secs. 25, 30, 31, and 36, on the E. bdy. of the Tp.

S. 89° 32' W., bet. secs. 25 and 36.

Descend 40 ft. over broken NW. slope, through moderate timber and dense undergrowth.

5.95 Old Highway No. 101, asphalt surfaced, 30 lks. wide, bears N. 7° E. and S. 7° W.

8.06 From this point an axle, loosely set, projecting 16 ins. above the ground, established by person(s) unknown, bears N., 15 lks. dist.

20.125 Point for the E 1/16 sec. cor. of secs. 25 and 36.

Set an iron pipe, 28 ins. long, 2 1/2 ins. diam., 23 ins. in the ground, with brass cap mkd.

E 1/16 $\frac{S\ 25}{S\ 36}$
1982

from which

A cedar, 13 ins. diam., bears N. 10 3/4° W., 25 lks. dist., mkd. E 1/16 S25 BT.

A fir, 25 ins. diam., bears S. 53 3/4° E., 65 1/2 lks. dist., mkd. E 1/16 S36 BT.

Set a steel fence post alongside the iron pipe.

Ascend 130 ft. over broken NW. slope.

26.60 Leave timber and undergrowth, edge bears N. 40° E. and S. 40° W.; enter rolling sand dunes through widely scattering timber and undergrowth.

40.25 Point for the 1/4 sec. cor. of secs. 25 and 36, at proportionate distance; there is no remaining evidence of the original corner.

Set an aluminum rod, 17 ft. long, 5/8 in. diam., 16 ft. in the ground, in concrete, with aluminum cap mkd.

T 22 S R 13 W
1/4 $\frac{S\ 25}{S\ 36}$
1982

from which

A pine, 8 ins. diam., bears N. 16 1/2° E., 923 lks. dist., mkd. 1/4 S25 BT.

No suitable tree available within limits in sec. 36.