

# County Surveyor's Record, Douglas County, Oregon

17077

Dependent Resurvey, Portion of S. Bdy.,  
T. 29 S., R. 9 W., Willamette Meridian, Oregon

**CHAINS**

- A fir, 21 ins. diam., bears N. 80° E., 32 lks. dist., with healed blaze.
- A fir, 10 ins. diam., bears S. 24 1/2° E., 12 lks. dist., with healed blaze.
- A fir, 11 ins. diam., bears S. 64 1/4° W., 34 1/2 lks. dist., with healed blaze.
- A fir, 8 ins. diam., bears N. 34° W., 14 lks. dist., with healed blaze.

N. 89° 47' W., bet. secs. 6 and 31, marking and blazing the true line.

Descend 25 ft. over SW. slope, through moderate timber and dense undergrowth.

2.15 Creek, 4 lks. wide, course S. 10° W.; asc. 310 ft. over broken SE. slope.

11.15 Edge of meadow, bears N. 30° E. and S. 30° W.; thence across meadow.

14.25 Edge of meadow, bears N. 60° E. and S. 60° W.; enter timber.

15.75 Top of ascent, slopes SW.; desc. 175 ft. over broken W. slope.

28.05 An original line tree, a fir, 66 ins. diam., with two notches each on E. and W. sides.

\_\_\_\_\_

N. 89° 47' W., beginning new measurement.

10.83 Point for the 1/4 sec. cor. of sec. 31 only.

Set an aluminum post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with aluminum cap mkd.

T 29 S R 9 W  
1/4 S 31  
T 30 S R 9 W  
1982

from which

A fir, 23 ins. diam., bears N. 34° E., 50 1/2 lks. dist., mkd. 1/4 S31 BT.

A hemlock, 18 ins. diam., bears N. 25 1/2° W., 80 lks. dist., mkd. 1/4 S31 BT.

Descend 5 ft. over W. slope.

11.96 The 1/4 sec. cor. of sec. 6 only, on the N. bdy. of T. 30 S., R. 9 W., determined from the remains of the original bearing trees

A decayed fir snag, 45 ins. diam., bears N. 45° E., 66 lks. dist., no marks visible on decayed blaze.

A cedar root crown, size indeterminate, bears S. 47° W., 57 lks. dist., no marks remaining.

and the remains of a bearing tree mkd. by Porter