

County Surveyor's Record, Douglas County, Oregon

17093

Subdivision of Sec. 31,
T. 29 S., R. 9 W., Willamette Meridian, Oregon

CHAINS

39.94

The E 1/16 sec. cor. of secs. 30 and 31.

From the N 1/16 sec. cor. of secs. 31 and 32.

S. 89° 50' W., on the E. and W. center line of the NE 1/4 of sec. 31.

Ascend 10 ft. over SE. slope, through logged area and light undergrowth.

9.80

Spur ridge, bears N. 80° E. and S. 80° W.; desc. 100 ft. over NW. slope.

19.82

The NE 1/16 sec. cor. of sec. 31.

Descend 105 ft. over NW. slope; also enter timber, edge bears N. 10° W. and S.

30.55

Spur, slopes N. 80° W.; desc. 160 ft. over broken SW. slope.

39.63

The center N 1/16 sec. cor. of sec. 31.

From the W 1/16 sec. cor. of sec. 31 only, on the S. bdy. of sec. 31.

N. 0° 34' W., on the N. and S. center line of the SW 1/4 of sec. 31.

Descend 105 ft. over broken W. slope, through moderate timber and undergrowth.

12.65

Creek, 5 lks. wide, course S. 5° W.; asc. 55 ft. over broken SE. slope.

20.06

Point for the SW 1/16 sec. cor. of sec. 31, at intersection with the E. and W. center line of the SW 1/4.

Set an aluminum post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with aluminum cap mkd.

SW 1/16 S 31
1982

from which

A hemlock, 43 ins. diam., bears N. 1/2° E., 20 lks. dist., mkd. SW 1/16 S31 BT.

A fir, 74 ins. diam., bears S. 31 1/2° W., 71 lks. dist., mkd. SW 1/16 S31 BT.

Ascend 355 ft. over broken SE. slope.

40.12

The center W 1/16 sec. cor. of sec. 31.

From the center S 1/16 sec. cor. of sec. 31.

S. 89° 57' W., on the E. and W. center line of the SW 1/4 of sec. 31.

Descend 395 ft. over broken S. slope, through moderate timber and undergrowth.

18.65

Creek, 4 lks. wide, course S.; asc. 40 ft. over SE. slope.