

# County Surveyor's Record, Douglas County, Oregon

17096

Remonumentation of Certain Original Corner Points,  
T. 29 S., R. 9 W., Willamette Meridian, Oregon

CHAINS

The remonumentation of these original corner points was made at the request of the Coos Bay District Manager for administrative purposes of the Bureau of Land Management.

(Remonumenting corners established by  
William S. Chapman in 1875)

The 1/4 sec. cor. of secs. 7 and 18, perpetuated and recorded by C.S. Lehmanowsky, Registered Professional Engineer No. 1768, in 1957, determined from the remains of an original bearing tree

A root hole, bears N. 10° E., 18 lks. dist., alongside of which is a downed cedar, 14 ins. diam., with fragmentary scribe marks visible on open blaze.

and the remains of bearing trees mkd. by Lehmanowsky

A cedar, 25 ins. diam., bears N. 34° E., 60 lks. dist., with healed blaze.

A cedar snag, 45 ins. diam., bears S. 41 1/2° E., 63 lks. dist., with scribe marks 1/4 BT visible on partially healed blaze.

At the corner point

Set an iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with brass cap mkd.

T 29 S R 9 W  
1/4  $\frac{S 7}{S 18}$   
1979

from which a new bearing tree

A cedar, 7 ins. diam., bears S. 11 1/4° W., 52 lks. dist., mkd. 1/4 S18 BT.

The cor. is located 30 lks. W. of creek, 1 lk. wide, course S.

The 1/4 sec. cor. of secs. 7 and 8, perpetuated and recorded by Forrest J. LaFlamme, Registered Land Surveyor No. 473, in 1962, determined from the remains of the original bearing trees

A decayed fir stump, size indeterminate, bears S. 85° E., 8 lks. dist., no marks visible.

A cedar snag, 20 ins. diam., bears N. 65° W., 58 lks. dist., with scribe mark 4 visible on opened blaze.

and the remains of a bearing tree mkd. by LaFlamme

A sawed fir stump, 44 ins. diam., bears N. 46 1/2° E., 35 lks. dist., with scribe marks 1/4 S8 BT visible on open blaze.

At the corner point

Set an iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with brass cap mkd.