

County Surveyor's Record, Douglas County, Oregon

17110

Dependent Resurvey, Portion of Subdivisional Lines,
T. 20 S., R. 12 W., Willamette Meridian, Oregon

CHAINS

A spruce, 15 ins. diam., bears S. 24° W., 26 1/2 lks. dist., with healed blaze.

and a bearing tree mkd. by Foeste

A spruce, 9 ins. diam., bears N. 24° E., 51 1/2 lks. dist., with healed blaze.

N. 89° 02' W., beginning new measurement.

Continue over nearly level swampy ground.

13.60 Begin ascent; asc. 50 ft. over broken E. slope.

20.85 Gravelled road, 20 lks. wide, bears N. 10° W. and S. 10° E.

23.10 Spur ridge, bears N. and S.; desc. 50 ft. over W. slope.

27.55 Creek, 5 lks. wide, course S. 10° E.; asc. 150 ft. over broken SE. slope.

29.50 Gravelled road, 20 lks. wide, bears N. and S.

40.41 The cor. of secs. 3, 4, 9, and 10, perpetuated and recorded by John M. Powell for the County Surveyor, in 1971, monumented with an iron pipe, 2 ins. diam., firmly set, projecting 12 ins. above ground, with brass cap mkd.

T 20 S
S 4 S 3
S 9 S 10
R 12 W
1971

FD OK
BY R. Ware
4/95 M122-4

from which the remains of bearing trees mkd. by Byars

A root hole, bears S. 60° E., 18 lks. dist.

A root hole, bears S. 40° W., 26 lks. dist., alongside of which is lying a hemlock, 16 ins. diam., with scribe marks BT visible on opened blaze.

and bearing trees mkd. by Powell

A spruce, 12 ins. diam., bears N. 62° E., 19 1/2 lks. dist., with healed blaze.

A hemlock, 10 ins. diam., bears S. 11° E., 31 lks. dist., with scribe marks T20S R12W S10 BT visible on partially healed blaze.

A hemlock, 17 ins. diam., bears S. 83° W., 11 1/2 lks. dist., with healed blaze.

A cedar, 8 ins. diam., bears N. 11° W., 4 1/2 lks. dist., with scribe marks T20S R12W S4 BT visible on partially healed blaze.

Land, rolling.
Soil, sandy loam.
Timber, fir, spruce, hemlock, cedar, alder, and chinquapin; undergrowth, salal, huckleberry, Oregon grape, vine maple, Scotch broom, rhododendron, and blackberry.