

County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Portion of Subdivisional Lines,
T. 20 S., R. 12 W., Willamette Meridian, Oregon

17113

CHAINS	
	<p>A spruce, 11 ins. diam., bears S. 61 1/4° E., 51 lks. dist., with scribe marks T21S R12W S4 BT visible on partially healed blaze.</p> <p>A spruce, 13 ins. diam., bears S. 70° W., 127 lks. dist., with scribe marks T21S R12W S5 BT visible on partially healed blaze.</p> <p>A spruce, 10 ins. diam., bears N. 68 1/4° W., 135 lks. dist., with scribe marks T20S R12W S32 BT visible on partially healed blaze.</p> <p>N. 0° 43' E., bet. secs. 32 and 33. Over nearly level swampy ground, through moderate timber and heavy undergrowth.</p>
7.70	<p>Creek, 2 lks. wide, course S. 50° W.; asc. 300 ft. over broken SW. slope.</p>
11.55	<p>U.S. Highway No. 101, asphalt surface, 80 lks. wide, bears N. 50° W. and S. 50° E.</p>
29.40	<p>Spur, slopes NW.; desc. 220 ft. over broken NE. slope.</p>
40.13	<p>The 1/4 sec. cor. of secs. 32 and 33, reestablished at proportionate distance and recorded by W. G. Corbitt for Crown Zellerbach Corporation, in 1941-43, and is accepted as the best available evidence of the position of the original corner, monumented with an iron pipe, 2 ins. diam., firmly set flush with the ground, from which the remains of bearing trees mkd. by Corbitt:</p> <p style="margin-left: 40px;">A rotted spruce stump, 5 ft. diam., bears N. 11° E., 114 lks. dist., no marks remaining.</p> <p style="margin-left: 40px;">A rotted hemlock stump, size indeterminate, bears S. 48 1/2° W., 13 lks. dist., no marks remaining.</p> <p>At the corner point</p> <p style="margin-left: 40px;">Set an aluminum post, 28 ins. long, 2 1/2 ins. diam., 25 ins. in the ground, with aluminum cap mkd.</p> <div style="margin-left: 100px; text-align: center;"> <p>T 20 S R 12 W 1/4 S 32 S 33 1981</p> </div> <div style="margin-left: 150px; text-align: right; font-family: cursive;"> <p>FDOK BY R. Word 4/95 M122-3A</p> </div> <p>from which new bearing trees</p> <p style="margin-left: 40px;">A spruce, 32 ins. diam., bears N. 44 3/4° E., 33 lks. dist., mkd. 1/4 S33 BT.</p> <p style="margin-left: 40px;">A spruce, 15 ins. diam., bears S. 26° W., 22 lks. dist., mkd. 1/4 S32 BT.</p> <p style="margin-left: 40px;">Deposit the iron pipe alongside the aluminum post.</p> <hr style="width: 20%; margin-left: 40px;"/> <p>N. 0° 43' E., beginning new measurement.</p> <p>Descend 100 ft. over broken NE. slope.</p>
9.85	<p>Bottom of descent, slopes NW.; asc. 140 ft. over broken SW. slope.</p>
36.15	<p>Top of ascent, slopes NW.; desc. 80 ft. over broken N. slope.</p>