

# County Surveyor's Record, Douglas County, Oregon

17114

Dependent Resurvey, Portion of Subdivisional Lines,  
T. 20 S., R. 12 W., Willamette Meridian, Oregon

**CHAINS**

40.13

The cor. of secs. 28, 29, 32, and 33, monumented with the remains of the original corner tree, a sawed and rotted spruce stump, 60 ins. diam., no marks remaining, from which the remains of the original bearing trees:

A sawed spruce stump, 60 ins. diam., bears  
N. 85° E., 22 lks. dist., no marks visible  
on opened blaze.

A sawed spruce stump, 70 ins. diam., bears  
S. 41° E., 65 lks. dist., no marks visible.

At the corner point

Set an aluminum rod, 4 ft. long, 5/8 in. diam., 36 ins. into center of original corner tree stump, with aluminum cap mkd.

T 20 S	R 12 W
S 29	S 28
S 32	S 33
1981	

from which new bearing trees

A fir, 7 ins. diam., bears N. 64 1/2° E., 47 lks.  
dist., mkd. T20S R12W S28 BT.

A spruce, 13 ins. diam., bears S. 18 3/4° E.,  
70 lks. dist., mkd. T20S R12W S33 BT.

A spruce, 5 ins. diam., bears S. 48 3/4° W.,  
8 lks. dist., mkd. T20S R12W S32 BT.

A spruce, 13 ins. diam., bears N. 74 1/2° W., 55 1/2  
lks. dist., mkd. T20S R12W S29 BT.

Land, mountainous.

Soil, sandy loam.

Timber, spruce, fir, hemlock, cedar, alder, and chinquapin; undergrowth, huckleberry, salal, rhododendron, Oregon grape, young timber, Scotch broom, willow, and manzanita.

N. 1° 17' W., bet. secs. 28 and 29.

Descend 95 ft. over N. slope, through moderate timber and dense undergrowth.

2.45

The meander cor. of secs. 28 and 29, on the S. shore of Tahkenitch Lake, determined from the remains of the original bearing trees:

A rotted spruce stump, 32 ins. diam., bears  
S. 62° E., 34 lks. dist., with scribe marks  
S28 T28S R12W visible on open blaze.  
(Record and slope dist., 40 lks.)

A sawed spruce stump, 60 ins. diam., bears  
S. 26° W., 5 lks. dist., with axe marks visible.

At the corner point

Set an aluminum rod, 4 ft. long, 5/8 in. diam., 30 ins. in the ground, with aluminum cap mkd.