

County Surveyor's Record, Douglas County, Oregon

17117

Dependent Resurvey, Portion of Subdivisional Lines,
T. 20 S., R. 12 W., Willamette Meridian, Oregon

CHAINS	
	Descend 40 ft. over broken NW. slope, through scattering timber and dense undergrowth.
10.05	Ravine, drains S. 60° W.; asc. 100 ft. over S. slope.
18.55	Top of ascent, slopes W.; desc. 90 ft. over NW. slope.
20.47	Point for the S 1/16 sec. cor. of secs. 16 and 17. Set an iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with brass cap mkd. <div style="text-align: center;"> S 1/16 S 17 S 16 1982 </div> from which <div style="margin-left: 40px;"> A spruce, 24 ins. diam., bears S. 73 1/4° E., 32 lks. dist., mkd. S 1/16 S16 BT. A spruce, 15 ins. diam., bears N. 87 1/4° W., 46 lks. dist., mkd. S 1/16 S17 BT. </div> Descend 110 ft. over N. slope.
26.90	Ravine drains W.; asc. 45 ft. over SW. slope.
28.65	Top of ascent, slopes W.; desc. 120 ft. over broken NW. slope.
35.75	S. shore of lake, bears N. 40° E. and S. 40° W.; thence across lake.
38.40	N. shore of lake, bears N. 65° E. and S. 65° W.; asc. 50 ft. over S. slope, through scattering timber and dense undergrowth.
40.94	Point for the 1/4 sec. cor. of secs. 16 and 17, at proportionate distance; no corner was established during the original survey. Set an iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with brass cap mkd. <div style="text-align: center;"> T 20 S R 12 W 1/4 S 17 S 16 1982 </div> from which <div style="margin-left: 40px;"> A fir, 10 ins. diam., bears N. 86° E., 7 lks. dist., mkd. 1/4 S16 BT. A spruce, 10 ins. diam., bears S. 54° W., 11 1/2 lks. dist., mkd. 1/4 S17 BT. </div> Ascend 140 ft. over SE. slope.
55.05	Top of ascent, slopes E.; desc. 50 ft. over broken NE. slope.
61.41	Point for the N 1/16 sec. cor. of secs. 16 and 17. Set an iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with brass cap mkd.

FD DE 134 & 140
 4/95 M. 224