

County Surveyor's Record, Douglas County, Oregon

17120

Dependent Resurvey, Portion of Subdivisional Lines,
T. 20 S., R. 12 W., Willamette Meridian, Oregon

CHAINS													
	Reset iron pipe alongside aluminum post.												
	N. 3° 27' W., beginning new measurement.												
	Descend slightly over broken NW. slope.												
33.25	U. S. Highway No. 101, asphalt surface, 40 lks. wide, bears N. 25° E. and S. 25° W.												
41.46	Point for the cor. of secs. 4, 5, 8, and 9, and meander cor. on the E. shore of Carter Lake, determined by extending the line westerly from the 1/4 sec. cor. of secs. 4, and 9, through a point, hereinafter described, established by H. A. Stoddart, Engineer for the Bureau of Public Roads, in 1931, at a distance recorded by Stoddart to the cor. of secs. 4, 5, 8, and 9, when original evidence was in existence.												
	Set an iron post, 28 ins. long, 2 1/2 ins. diam., 25 ins. in the ground, in concrete with brass cap mkd.												
	<table style="margin: auto; border-collapse: collapse;"> <tr> <td></td> <td style="text-align: center;">T 20 S</td> <td style="text-align: center;">R 12 W</td> </tr> <tr> <td style="text-align: center;">MC</td> <td style="text-align: center;">S 5 S 4</td> <td></td> </tr> <tr> <td></td> <td style="text-align: center;">S 8 S 9</td> <td></td> </tr> <tr> <td></td> <td colspan="2" style="text-align: center;">1982</td> </tr> </table>		T 20 S	R 12 W	MC	S 5 S 4			S 8 S 9			1982	
	T 20 S	R 12 W											
MC	S 5 S 4												
	S 8 S 9												
	1982												
	from which												
	An iron post, 28 ins. long, 2 1/2 ins. diam., set 27 ins. in the ground, for a reference monument, bears N. 63° E., 58 lks. dist., with brass cap mkd. RM T20S R12W S4 38.3 FT TO COR 1982, and an arrow pointing to the corner.												
	An iron post, 28 ins. long, 2 1/2 ins. daim., set 27 ins. in the ground, for a reference monument, bears S. 27° E., 48 1/2 lks. dist., with brass cap mkd. RM T20S R12W S9 32 FT TO COR 1982, and an arrow pointing to the corner.												
	Corner is located on the E. shore of Carter Lake, edge bears N. 30° E. and S. 30° W.												
	Land, rolling. Soil, sandy loam. Timber, spruce, fir, hemlock, cedar, and alder; undergrowth, salal, huckleberry, rhododendron, blackberry, willow, Scotch broom, and fern.												
	From the cor. of secs. 3, 4, 9, and 10.												
	N. 89° 58' W., bet. secs. 4 and 9.												
	Ascend slightly over SE. slope, through moderate timber and undergrowth.												
13.20	Spur, slopes N. 40° E.; desc. 50 ft. over broken NW. slope.												
19.10	Ravine, drains N. 30° E.; asc. 60 ft. over NE. slope.												
33.20	Top of ascent, slopes N.; desc. 50 ft. over broken NW. slope.												
40.43	The 1/4 sec. cor. of secs. 4 and 9, perpetuated and recorded by W.G. Corbitt for Crown Zellerbach Corporation in 1941-43, subsequently perpetuated and recorded by Karl F. Foeste, Registered Land Surveyor, No. 849, in 1974, monu-												