

# County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Portion of Subdivisional Lines,  
T. 20 S., R. 12 W., Willamette Meridian, Oregon

17129

**CHAINS**

Set a steel fence post alongside iron post.

The corner is located on a low sandy spur, slopes N.


Descend slightly over NW. slope.

48.42 True point for the meander cor. of secs. 20 and 29, on the left bank of Tahkenitch Creek, at proportionate distance; there is no remaining evidence of the original corner. Point is located in Tahkenitch Creek where it is impracticable to establish a permanent monument.

48.80 Tahkenitch Creek, 100 lks. wide, course S. 70° W.; asc. slightly over sand bank.

50.22 Point selected for the witness corner to the meander cor. of secs. 20 and 29, on the left bank of Tahkenitch Creek.

Set an iron post, 28 ins. long, 2 1/2 ins. diam., 22 ins. in the ground, in concrete, with brass cap mkd.



from which

A spruce, 6 ins. diam., bears N. 55 1/2° E.,  
55 lks. dist., mkd. X BT.

Set a steel fence post alongside the iron post.

Descend slightly over sand bank.

51.20 Tahkenitch Creek, 100 lks. wide, course N. 20° E.; asc. 120 ft. over steep sandy E. slope.


51.72 Point for the meander cor. of secs. 20 and 29, on the left bank of Tahkenitch Creek, at proportionate distance; there is no remaining evidence of the original corner. No permanent monument established.

54.00 Top of sand ridge, bears N. and S.; desc. 120 ft. over W. slope.

58.30 Base of slope, bears N. and S.; asc. slightly over rolling sand dunes, through scattering timber and dense undergrowth.

60.93 Point for the W 1/16 sec. cor. of secs. 20 and 29.

Set an aluminum post, 28 ins. long, 2 1/2 ins. diam., 22 ins. in the ground, in concrete, with aluminum cap mkd.



from which

A pine, 9 ins. diam., bears N. 62° W., 27 lks.  
dist., mkd. W 1/16 S20 BT.

No suitable tree available in sec. 29.

Set a steel fence post alongside aluminum post.