

County Surveyor's Record, Douglas County, Oregon

17145

Subdivision of Sec. 4,
T. 20 S., R. 12 W., Willamette Meridian, Oregon

<p>CHAINS 9.00</p> <p>19.555</p> <p>20.50</p> <p>24.00</p> <p>39.13</p>	<p>W. shore of Loon Lake, bears N. and S.; asc. slightly over nearly level land.</p> <p>The NW 1//6 sec. cor. of sec. 4.</p> <p>Continue over nearly level land.</p> <p>Foot of hill, bears N. and S.; asc. 90 ft. over E. slope.</p> <p>Ridge, bears N. and S.; desc. 100 ft. over W. slope, also; leave timber and undergrowth, enter rolling sand dunes with scattering timber and undergrowth.</p> <p>The N 1/16 sec. cor. of secs. 4 and 5.</p>
<p>Subdivision of Section 8, T. 20 S., R. 12 W., Willamette Meridian, Oregon</p>	
<p>20.46</p> <p>40.92</p>	<p>From the 1/4 sec. cor. of secs. 8 and 17.</p> <p>N. 2° 51' W., on the N. and S. center line of sec. 8.</p> <p>Across nearly level rolling sand dunes, through scattering timber and undergrowth.</p> <p>Point for the center S 1/16 sec. cor. of sec. 8.</p> <p>Set an iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, in concrete, with brass cap mkd.</p> <div style="text-align: center; margin: 10px 0;"> <p style="margin: 0;">S 1/16 C S 8 C 1982</p> </div> <p>No suitable trees available.</p> <p>Continue over nearly level land.</p> <p>Point for the center 1/4 sec. cor. of sec. 8, at intersection with the E. and W. center line.</p> <p>Set an iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, in concrete, with brass cap mkd.</p> <div style="text-align: center; margin: 10px 0;"> <p>T 20 S R 12 W C 1/4 S 8 1982</p> </div> <p>from which</p> <p style="margin-left: 40px;">A pine, 10 ins. diam., bears S. 16° E., 126 lks. dist., mkd. C 1/4 S8 BT.</p> <p style="margin-left: 40px;">A pine, 6 ins. diam., bears S. 83° W., 103 1/2 lks. dist., mkd. X BT.</p> <p>Continue over nearly level land.</p>
<p>82.55</p>	<p>The 1/4 sec. cor. of secs. 5 and 8.</p>
<p>From the 1/4 sec. cor. of secs. 8 and 9.</p> <p>West, on the E. and W. center line of sec. 8.</p> <p>Descend 180 ft. over broken NW. slope, through moderate timber and dense undergrowth.</p>	