

County Surveyor's Record, Douglas County, Oregon

17151

Subdivision of Sec. 17,
T. 20 S., R. 12 W., Willamette Meridian, Oregon

CHAINS	
	Ascend 60 ft. over NE. slope, through moderate timber and dense undergrowth.
3.50	Top of ascent, slopes N.; desc. 250 ft. over NW. slope.
19.50	U.S. Highway No. 101, asphalt surface, 70 lks. wide, bears N. and S.
21.70	Ravine, drains S.; asc. 40 ft. over E. slope, also leave timber and undergrowth, edge bears N. and S.; enter rolling sand dunes with scattering timber and undergrowth.
23.30	Top of ascent, slopes N.; continue over nearly level broken W. slope.
40.00	Enter moderate timber and undergrowth, edge bears NE. and SW.
40.45	The center S 1/16 sec. cor. of sec. 17.
<p>Subdivision of Section 20, T. 20 S., R. 12 W., Willamette Meridian, Oregon</p>	
	From the 1/4 sec. cor. of secs. 20 and 29.
	N. 0° 21' W., on the N. and S. center line of sec. 20.
	Across swamp.
6.50	Leave swamp, edge bears E. and W.; asc. 105 ft. over broken sand dunes, through scattering timber and dense undergrowth.
39.97	Point for the center 1/4 sec. cor. of sec. 20, at intersection with the E. and W. center line.
	Set an aluminum post, 28 ins. long, 2 1/2 ins. diam., 23 ins. in the ground, with aluminum cap mkd.
	<p>T 20 S R 12 W C 1/4 S 20 1982</p>
	from which
	A pine, 17 ins. diam., bears N. 62° E., 23 lks. dist., mkd. C 1/4 S20 BT.
	A spruce, 10 ins. diam., bears N. 41 1/4° W., 36 lks. dist., mkd. C 1/4 S20 BT.
	Set a steel fence post alongside aluminum post.
	Ascend 35 ft. over broken W. slope.
43.00	Enter open sand dunes, edge bears E. and W.
59.00	Leave open sand dunes; enter scattering timber and dense undergrowth, edge bears NE. and SW.
60.015	Point for the center N 1/16 sec. cor. of sec. 20.
	Set an iron post, 28 ins. long, 2 1/2 ins. diam., 24 ins. in the ground, with brass cap mkd.