

# County Surveyor's Record, Douglas County, Oregon

17204

Dependent Resurvey, Portion of Subdivisional Lines,  
T. 21 S., R. 12 W., Willamette Meridian, Oregon

CHAINS																	
	<p>From this point, the NW. cor. of Donation Land Claim No. 39, bears S. 40° 00' W., 36.51 chs. dist., hereinafter described.</p> <p>Ascend 70 ft. over SW. slope, changing to S. slope.</p>																
71.70	<p>Top of ascent, slopes E.; desc. 15 ft. over gently rolling N. slope.</p>																
80.06	<p>The cor. of secs. 7, 8, 17, and 18, determined from the remains of the original bearing trees:</p> <p style="margin-left: 40px;">A sawed spruce stump, 30 ins. diam., bears N. 6° E., 52 lks. dist., no marks visible. (Record, 50 lks.)</p> <p style="margin-left: 40px;">A decayed hemlock stump, 24 ins. diam., bears S. 68° E., 89 1/2 lks. dist., no marks visible. (Record, 88 lks.)</p> <p style="margin-left: 40px;">A sawed spruce stump, 36 ins. diam., bears S. 52 1/2° W., 44 lks. dist., no marks visible. (Record, 42 lks.)</p> <p style="margin-left: 40px;">A root hole, bears N. 30° W., 8 lks. dist., with a down and decayed hemlock alongside, 12 ins. diam., no marks visible.</p> <p>At the corner point</p> <p>Set an aluminum post, 28 ins. long, 2 1/2 ins. diam., 22 ins. in the ground, with aluminum cap mkd.</p> <div style="text-align: center; margin: 10px 0;"> <table style="margin: auto; border-collapse: collapse;"> <tr> <td colspan="2">T 21 S</td> <td colspan="2">R 12 W</td> </tr> <tr> <td style="border-right: 1px solid black; padding: 0 5px;">S 7</td> <td style="padding: 0 5px;">S 8</td> <td colspan="2"></td> </tr> <tr> <td style="border-right: 1px solid black; padding: 0 5px;">S 18</td> <td style="padding: 0 5px;">S 17</td> <td colspan="2"></td> </tr> <tr> <td colspan="4" style="text-align: center;">1981</td> </tr> </table> </div> <p>from which new bearing trees</p> <p style="margin-left: 40px;">A spruce, 15 ins. diam., bears N. 63 1/2° E., 24 lks. dist., mkd. T21S R12W S8 BT.</p> <p style="margin-left: 40px;">A spruce, 15 ins. diam., bears S. 18° E., 8 1/2 lks. dist., mkd. T21S R12W S17 BT.</p> <p style="margin-left: 40px;">A spruce, 24 ins. diam., bears S. 85° W., 43 lks. dist., mkd. T21S R12W S18 BT.</p> <p style="margin-left: 40px;">A spruce, 12 ins. diam., bears N. 54° W., 23 lks. dist., mkd. T21S R12W S7 BT.</p> <p>Land, rolling hills. Soil, sandy clay loam. Timber, spruce, hemlock, fir, and pine; undergrowth, rhododendron, salal, thimbleberry, salmonberry, blackberry, huckleberry, manzanita, and fern.</p>	T 21 S		R 12 W		S 7	S 8			S 18	S 17			1981			
T 21 S		R 12 W															
S 7	S 8																
S 18	S 17																
1981																	
1.60	<p>From the cor. of secs. 8, 9, 16, and 17.</p> <p>N. 88° 44' W., bet. secs. 8 and 17.</p> <p>Descend 55 ft. over NW. slope, through moderate timber and dense undergrowth.</p> <p>Gravelled road, 25 lks. wide, bears N. 50° E. and S. 50° W.</p>																