

# County Surveyor's Record, Douglas County, Oregon

Dependent Resurvey, Portion of Subdivisional Lines,  
T. 21 S., R. 12 W., Willamette Meridian, Oregon

17208

**CHAINS**

T 21 S R 12 W  
S 6 | S 5  
S 7 | S 8  
1981

from which new bearing trees

A spruce, 12 ins. diam., bears N. 21 1/2° E., 18 1/2 lks. dist., mkd. T21S R12W S5 BT.

A spruce, 20 ins. diam., bears S. 23° E., 41 lks. dist., mkd. T21S R12W S8 BT.

A spruce, 12 ins. diam., bears S. 11° W., 57 lks. dist., mkd. T21S R12W S7 BT.

A spruce, 12 ins. diam., bears N. 10° W., 46 lks. dist., mkd. T21S R12W S6 BT.

Land, rolling to mountainous.

Soil, sandy loam.

Timber, spruce, hemlock, fir, and cedar; undergrowth, salal, salmonberry, thimbleberry, huckleberry, and fern.

From the cor. of secs. 4, 5, 8, and 9.

N. 87° 33' W., bet. secs. 5 and 8.

Descend 5 ft. over nearly level land, through heavy timber and dense undergrowth.

0.30 Creek, 2 lks. wide, course S. 30° E.; asc. 425 ft. over broken E. slope.

21.80 Ridge, bears N. 10° W. and S. 10° E.; desc. 100 ft. over broken SW. slope.

40.89 Point for the 1/4 sec. cor. of secs. 5 and 8, at proportionate distance; there is no remaining evidence of the original corner.

Set an aluminum post, 28 ins. long, 2 1/2 ins. diam., 22 ins. in the ground, with aluminum cap mkd.

T 21 S R 12 W  
1/4 S 5  
S 8  
1981

from which

A hemlock, 30 ins. diam., bears S. 85 1/2° E., 32 lks. dist., mkd. 1/4 S8 BT.

A hemlock, 13 ins. diam., bears N. 70° W., 19 lks. dist., mkd. 1/4 S5 BT.

Descend 290 ft. over broken SW. slope.

75.40 Creek, 2 lks. wide, course S. 85° W.; asc. 5 ft. along broken S. slope.

81.78 The cor. of secs. 5, 6, 7, and 8.

Land, mountainous.

Soil, sandy loam.

Timber, spruce, fir, hemlock, alder, and cedar; undergrowth, salal, salmonberry, thimbleberry, and fern.