

County Surveyor's Record, Douglas County, Oregon

17217

Adjusted Meanders, Portion of Right Bank of
Umpqua River, T. 21 S., R. 12 W.,
Willamette Meridian, Oregon

CHAINS	
	<p style="text-align: right;">W. center line of the SE 1/4 of sec. 19, hereinafter described.</p> <p>S. 3° 09' W., 5.68 chs.</p> <p>S. 2° 07' E., 7.61 chs.</p> <p>S. 19° 02' W., 7.06 chs. The meander cor. of secs. 19 and 30, hereinbefore described.</p>
	<p>Subdivision of Section 5, T. 21 S., R. 12 W., Willamette Meridian, Oregon</p>
	<p>From the 1/4 sec. cor. of secs. 5 and 8.</p> <p>N. 2° 11' W., on the N. and S. center line of sec. 5.</p> <p>Ascend 50 ft. over S. slope, through heavy timber and medium undergrowth.</p>
1.20	Ridge bears E. and W.; desc. 395 ft. over broken N. slope.
19.85	Creek, 2 lks. wide, course N. 60° W.; thence over nearly level ground.
21.25	Creek, 2 lks. wide, course S. 75° W.; asc. 140 ft. over SW. slope.
25.65	Draw, slopes S. 50° W.; asc. slightly over broken S. slope.
27.20	Spur, slopes W.; desc. 55 ft. over N. slope.
28.95	Draw, slopes N. 50° W.; asc. 35 ft. over SW. slope.
34.00	Spur, slopes W.; desc. 50 ft. over NW. slope.
35.20	Creek, 1 lk. wide, course S. 65° W.; asc. 135 ft. over broken SW. slope.
37.60	<p>Point for the center 1/4 sec. cor. of sec. 5, at intersection with the E. and W. center line.</p> <p>Set an aluminum post, 28 ins. long, 2 1/2 ins. diam., 22 ins. in the ground, with aluminum cap mkd.</p> <p style="text-align: center;">T 21 S R 12 W C 1/4 S 5 1981</p> <p>from which</p> <p style="padding-left: 40px;">A spruce, 20 ins. diam., bears S. 21 3/4° E., 81 lks. dist., mkd. C 1/4 S5 BT.</p> <p style="padding-left: 40px;">A spruce, 37 ins. diam., bears S. 78 1/2° W., 98 lks. dist., mkd. C 1/4 S5 BT.</p> <p>Ascend 10 ft. over broken SW. slope.</p>
40.00	Saddle in ridge, bears E. and W.; desc. 145 ft. over N. slope.