

County Surveyor's Record, Douglas County, Oregon

17223

Subdivision of Sec. 17,
T. 21 S., R. 12 W., Willamette Meridian, Oregon

CHAINS

from which

A hemlock, 12 ins. diam., bears N. 41 1/2° E., 11 lks. dist., mkd. CW 1/16 S17 BT.

A hemlock, 20 ins. diam., bears S. 35 1/4° E., 17 lks. dist., mkd. CW 1/16 S17 BT.

Descend 15 ft. over E. slope.

20.95 Draw, drains N. 10° E.; asc. 10 ft. over W. slope.

22.60 Spur, slopes N.; desc. 10 ft. over NE. slope.

24.25 Draw, drains N. 50° W.; asc. 125 ft. over W. slope.

30.75 Ridge, bears N. 10° E. and S. 10° W.; desc. 100 ft. over broken SE. slope.

36.785 Intersect the S. bdy. of Donation Land Claim No. 39.

Point for crossing closing cor. on the E. and W. center line, with the S. bdy. of Donation Land Claim No. 39.

Set an aluminum post, 28 ins. long, 2 1/2 ins. diam., 23 ins. in the ground, with aluminum cap mkd.

$$C \frac{CCC}{S 17} C \frac{DLC}{39}$$

1981

from which

An alder, 8 ins. diam., bears S. 11 1/2° W., 46 lks. dist., mkd. S17 CCC BT.

A spruce, 25 ins. diam., bears N. 68 1/2° W., 43 lks. dist., mkd. S17 CCC BT.

From this point, the exterior cor. on the S. bdy. of Donation Land Claim No. 39, bears S. 44° 07' E., 4.94 chs. dist., hereinbefore described.

Descend 70 ft. over gentle SE. slope.

41.23 The center 1/4 sec. cor. of sec. 17.

Descend 80 ft. over broken SE. slope.

43.99 Point selected for the witness cor. to the special meander cor. on the E. and W. center line of sec. 17.

Set a brass tablet, 3 1/4 ins. diam., 3 1/2 in. stem, in drill hole, on top of rock ledge, with top mkd.

$$C \frac{WC}{S 17} C \quad SMC$$

1981

from which

An XBO, chiseled on a sandstone cliff, 4 ft. above the high water mark, bears N. 50° E., 6 lks. dist.

An XBO, chiseled on a sandstone cliff, 3 ft. above the high water mark, bears S. 50° W., 8 1/2 lks. dist.