

County Surveyor's Record, Douglas County, Oregon

Subdivision of Sec. 17,
T. 21 S., R. 12 W., Willamette Meridian, Oregon

17224

CHAINS	
54.37	<p>The corner is located on rock ledge on right bank of the Umpqua River, bears N. 50° E. and S. 50° W.</p> <p>Intersect the adjusted meander line of the right bank of the Umpqua River.</p> <p>True point for the special meander cor. on the E. and W. center line of sec. 17, with the adjusted meander line of the right bank of the Umpqua River; located in the tide plain of the Umpqua River where it is impractical to establish a permanent monument.</p>
15.30	<p>From the center W 1/16 sec. cor. of sec. 17.</p> <p>S. 2° 08' W., parallel with the W. bdy. of the sec., on the N. and S. center line of the SW 1/4 of sec. 17.</p> <p>Ascend 170 ft. over broken NE. slope, through medium timber and dense undergrowth.</p> <p>Ridge, bears N. 30° E. and S. 30° W.; desc. 135 ft. over broken SE. slope.</p>
20.01	<p>Point for the SW 1/16 sec. cor. of sec. 17, at intersection with the E. and W. center line of the SW 1/4.</p> <p>Set an aluminum post, 28 ins. long, 2 1/2 ins. diam., 22 ins. in the ground, with aluminum cap mkd.</p> <p style="text-align: center;">SW 1/16 S 17 1981</p> <p>from which</p> <p style="padding-left: 40px;">A fir, 75 ins. diam., bears S. 54 1/2° W., 116 1/2 lks. dist., mkd. SW 1/16 S17 BT.</p> <p style="padding-left: 40px;">A fir, 12 ins. diam., bears N. 52 1/2° W., 104 1/2 lks. dist., mkd. SW 1/16 S17 BT.</p> <p>Descend 185 ft. over steep, broken SE. slope.</p>
25.145	<p>Point selected for the witness cor. to the special meander cor. on the N. and S. center line of the SW 1/4 of sec. 17.</p> <p>Set a brass tablet, 3 1/4 ins. diam., 3 1/2 in. stem, in drill hole in exposed sandstone, with top mkd.</p> <div style="text-align: center; margin: 10px 0;"> <p>W C</p> <p>W</p> <p>S ↓ 17</p> <p>W</p> <p>SMC</p> <p>1981</p> </div> <p>from which</p> <p style="padding-left: 40px;">An XBO, chiseled in exposed sandstone, bears N. 78° E., 28 lks. dist.</p> <p style="padding-left: 40px;">An XBO, chiseled in exposed sandstone, bears N. 83° W., 12 lks. dist.</p> <p>The corner is located on right bank of the Umpqua River, bears NE. and SW.</p>
25.32	<p>Intersect the adjusted meander line of the right bank of the Umpqua River.</p>